

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS/FCI21008449/T1uf3			
MS FIRST CAPITAL INSURANCE LTD		Ref: 000/FCI21008449/T1uf3	
36 ROBINSON ROAD		Date: 12/08/2021	
#16-01 CITY HOUSES SINGAPORE 068877		Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHC 7572J	Veh. Inspected	FBJ 9735C
Policy No.		Coverage (\$)	0.00
Claim No.	D20003436MFSH	Excess (\$)	0.00
Assign From	WOO JUN KIATERIC	Assign Date	12/08/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	23/08/2020	Inspection Date	12/08/2021
Survey held at	SG MOTORS PTE LTD 8 KAKI BUKIT AVENUE 4, #03-03, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			