

辉陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

16/08/21
Monday
after 11am
LKK

28/07/2021

Owner: HYMS CAR LEASING PTE LTD

Not Withain
L1 Reg 8
2 days, Monday After Rain

ESTIMATE TO REPAIR TOYOTA PRIUS HYBRID 1.8S A - SMG2733P

1pc rear bumper
1pc rear bumper LH side retainer
1pc rear bumper diffuser
1pc rear bumper reinforcement
1pc rear bumper LH side lamp
1pc rear bumper LH side garnish
1pc rear bumper LH side inner shield

mgcm \$ 928.35 ✓
D1 \$ 141.40 ✓
N \$ 379.00 ✓
\$ 458.00 ✓
\$ 281.50 ✓
mgcm \$ 381.80 ✓
Pm \$ 285.50 X

less 25%

\$ 2,855.55
\$ 713.89
\$ 2,141.66

wiring
spray painting
labour charges
Total

\$ 50.00 15h
\$ 800.00 30d
\$ 800.00 22d
\$ 3,791.66

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

