

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEONG WEICHENG JEREMY
162B PUNGGOL CENTRAL
#08-71
SINGAPORE 822162

Estimate No: MC1902097
Date: 12 Aug 2021
Policy No: P10539983R00
Veh Reg No: SMK3343D
Make/Model: HYUNDAI AD AVANTE
1.6 GLS

ATTN:

Your Ref No: SMK3343D
Claim Type: Third Party
Accident Date: 09/08/2021
TP Veh Reg No: SMC6692T

Estimate Repair Cost to Vehicle No :SMK3343D

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT EMBLEM W HANDLE	1 PC	196.20	
2 REAR BOOT AVANTE LOGO	1 PC	31.20	
3 REAR BOOT S LOGO	1 PC	55.00	
4 REAR BOOT LOCK	1 PC	116.20	
5 REAR BUMPER	1 PC	459.40	
6 REAR BUMPER LOWER GARNISH	1 PC	353.50	
7 REAR BUMPER LAMP LH	1 PC	201.50	
8 REAR BUMPER SIDE RETAINER LH	1 PC	26.10	
9 REAR BUMPER CLIPS	10 PC	20.00	
10 REAR BUMPER NO PLATE GARNISH	1 PC	28.00	
11 REAR BUMPER NO PLATE LAMP LH & RH	2 PC	56.00	
12 REAR BUMPER BEAM	1 PC	294.80	
13 REAR BUMPER STAY LH	1 PC	78.60	
14 REAR BUMPER STAY RH - CHECK PRICE	1 PC	0.00	
15 REAR END PANEL	1 PC	454.60	
16 REAR END PANEL GARNISH	1 PC	59.80	
17 SMART KEY ANTENNA ASSY	1 PC	40.50	
		2,471.40	
	Less 20%	494.28	1,977.12
Special Nett			
18 REVERSE SENSOR	1 SET	200.00	
19 NUMBER PLATE (OPC)	1 PC	35.00	
		235.00	235.00
LABOUR			
20 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	
21 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	120.00	
22 TO ARRANGE, SUPPLY AND SEAL OFF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY.	1 PC	60.00	
23 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
24 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL.TO KNOCK & REPAIR REAR BOOT,SPARE TYRE PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	
25 TO SPRAY REAR BOOT,REAR BUMPER,REAR END PANEL.	1 PC	600.00	

Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEONG WEICHENG JEREMY
162B PUNGGOL CENTRAL
#08-71
SINGAPORE 822162

ATTN:

Your Ref No: SMK3343D
Claim Type: Third Party
Accident Date: 09/08/2021
TP Veh Reg No: SMC6692T

Estimate No: MC1902097
Date: 12 Aug 2021
Policy No: P10539983R00
Veh Reg No: SMK3343D
Make/Model: HYUNDAI AD AVANTE
1.6 GLS

Estimate Repair Cost to Vehicle No :SMK3343D

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		1,500.00	1,500.00
		Total	S\$ 3,712.12
		Add GST @ 7%	259.85
		Total Amount Payable	S\$ 3,971.97

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED SEVENTY ONE AND CENTS NINETY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY


Zila
AH Lim Motor Company
AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 777B

Vehicle Details

Vehicle No.: SMK3343D
Vehicle to be Exported: No
Intended Deregistration Date: 10 Aug 2021
Vehicle Make: HYUNDAI
Vehicle Model: AD AVANTE 1.6 GLS (A) S
Primary Colour: Blue
Manufacturing Year: 2019
Engine No.: G4FGKU126552
Chassis No.: KMHD841CMKU893763
Maximum Power Output: 93.8 kW (125 bhp)
Open Market Value: \$14,555.00
Original Registration Date: 05 Apr 2019
First Registration Date: 05 Apr 2019
Transfer Count: 0
Actual ARF Paid: \$14,555.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No
OPC Cash Rebate Eligibility Expiry Date: -
OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 04 Apr 2029
PARF Rebate Amount: \$10,916.00

Intended COE Rebate Details

COE Expiry Date: 04 Apr 2029
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$9,309.00
COE Rebate Amount: \$7,122.00
Total Rebate Amount: \$18,038.00

The information contained herein is correct as at 10 Aug 2021

OK