

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21008455/BEA3Q2**Date:** 09/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100447974
Claimant Vehicle No :	SLX7441X	Insured Vehicle No :	SKZ338J
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	3553997307SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX7441X	Engine No:	R16B25500426
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650JT000379
Reg. Date:	10/04/2018 (Man. Year: 2018)	Odometer:	79528 km
Colour:	Black		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,184.32	8,335.92	6,848.40	45.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,650.00	3,160.00	2,490.00	44.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,834.32	11,495.92	9,338.40	44.82
+ GST 7.00/7.00% (S\$)	1,458.40	804.71	653.69	44.82
Nett Amount (S\$)	22,292.72	12,300.63	9,992.09	44.82
+ Car Rental (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		13,908.08		
Global Sum Settlement (S\$)		13,900.00		

INSPECTION

Date of Assignment:	11/08/2021	Team Autopro Pte Ltd (sin Ming) (HQ)
Date Inspected:	12/08/2021 Inspected At:	160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
Estimated Period of Repair:	12.0 days	Singapore 575722

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Dented	789.60 FL	*655.20 FL
2	1	*BOOTLID LOGO	Necessary	69.50 FL	*40.00 FL
3	1	*BOOTLID EMBLEM CIVIC	Necessary	98.00 FL	*48.00 FL
4	1	*BOOTLID EMBLEM I-VTEC	Necessary	98.00 FL	*50.00 FL
5	2	*BOOTLID LAMP	Broken	972.60 FL	*510.00 FL
6	1	*BOOTLID INNER LOCK	Jammed	325.60 FL	*195.30 FL
7	1	*BOOTLID LOCK STRICKER	Not Damaged	68.20 FL	*- FL
8	1	*BOOTLID ANTENNA SENSOR	Broken	364.20 FL	*180.00 FL
9	1	*BOOTLID INNER TRIM BOARD	Not Damaged	204.60 FL	*- FL
10	1	*BOOTLID WEATHERSTRIP	Torn	372.90 FL	*144.20 FL
11	1	*BOOTLID OUTER GARNISH	Broken	348.60 FL	*215.00 FL
12	1	*BOOTLID NUMBER PLATE LAMP W/SWITCH	Not Damaged	155.30 FL	*- FL
13	1	*BOOTLID REVERSE CAMERA	Not Damaged	488.00 FL	*- FL
14	2	*BOOTLID HINGE	Repair	304.00 FL	*- FL
15	1	*REAR BUMPER	Broken	895.30 FL	*631.20 FL
16	1	*REAR BUMPER LOWER	Broken	386.00 FL	*178.00 FL
17	2	*REAR BUMPER SIDE RETAINER	Necessary	119.60 FL	*119.60 FL
18	1	*REAR BUMPER REINFORCEMENT	Bent	190.80 FL	*190.80 FL
19	2	*REAR BUMPER BRACKET	Broken	132.00 FL	*132.00 FL
20	2	*REAR BUMPER REFLECTOR	Broken	250.80 FL	*250.80 FL
21	2	*REAR BUMPER REFLECTOR GARNISH	Broken	421.80 FL	*171.60 FL
22	1	*REAR BUMPER REVERSE SENSOR (4 PCS)	Scratched (3 PCS ONLY)	860.00 FL	*456.90 FL
23	1	*REAR BUMPER REVERSE SENSOR WIRING HARNNES	Cut	298.00 FL	*252.30 FL
24	1	*REAR END PANEL	Dented	863.70 FL	*805.00 FL
25	1	*REAR END PANEL TOP GARNISH	Broken	208.60 FL	*208.60 FL
26	1	*SPARE TYRE PANEL	Dented	736.90 FL	*619.60 FL
27	1	*SPARE TYRE PANEL TOP BOARD	Broken	195.80 FL	*195.80 FL
28	1	*SPARE TYRE TOOL TRAY	Not Damaged	155.90 FL	*- FL
29	2	*REAR FENDER	Repair	1,936.20 FL	*- FL
30	2	*REAR FENDER INNER TRIM BOARD	Torn	597.40 FL	*597.40 FL
31	1	*REAR WINDSCREEN MOULDING	Not Necessary	198.00 FL	*- FL
32	1	*REAR CHASSIS RH	Bent	758.00 FL	*668.70 FL
33	2	*TAILLAMP	Broken	1,684.60 FL	*1,447.00 FL
34	2	*TAILLAMP BASE PANEL	Dented	579.40 FL	*579.40 FL
35	1	*SUNDRIES	Not Necessary	80.00 FS	*- FS
36	1	*BOOTLID SEALANT	Necessary	100.00 FS	*40.00 FS
37	2	*BOOTLID LAMP CLIPS	Not Necessary	100.00 FS	*- FS
38	2	*BOOTLID LAMP SEAL	Necessary	120.00 FS	*60.00 FS
39	1	*BOOTLID INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
40	1	*BOOTLID OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
41	1	*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
42	1	*REAR BUMPER LOWER CLIPS	Necessary	50.00 FS	*20.00 FS
43	2	*REAR BUMPER REFLECTOR GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
44	4	*REAR BUMPER REVERSE SENSOR SEAL	Necessary (3 PCS ONLY)	192.00 FS	*192.00 FS
45	1	*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
46	1	*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
47	1	*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
48	2	*REAR FENDER SEALANT	Not Necessary	200.00 FS	*- FS
49	2	*REAR FENDER INNER TRIM BOARD CLIPS	Necessary	100.00 FS	*40.00 FS
50	1	*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
51	1	*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
52	1	*REAR WINDSCREEN PRIMER & CLEANER	Not Necessary	80.00 FS	*- FS
53	1	*REAR CHASSIS SEALANT	Necessary	100.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	2		*TAILLAMP CLIPS	Necessary	100.00 FS	*20.00 FS
55	2		*TAILLAMP SEAL	Necessary	120.00 FS	*60.00 FS
56	2		*TAILLAMP BASE PANEL SEALANT	Necessary	200.00 FS	*30.00 FS
57	1		*REAR NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					18,409.90	10,244.40
- List Item Discount on L Items 20.00/20.00% (\$)					3,225.58	1,908.48
Total Parts (\$)					15,184.32	8,335.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR BOOTLID COMPONENT	New	150.00	80.00
2	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
3	R&R REVERSE CAMERA	New	100.00	0.00
4	R&R REAR WINDSCREEN	New	250.00	0.00
5	R&R REAR EXHAUST PIPE	New	150.00	70.00
6	CHECK WIRING	New	100.00	30.00
7	UPHOLSTERY	New	300.00	0.00
8	DIAGNOSTIC & RESET FAULT CODE	New	300.00	120.00
9	PANEL BEATING	New	2,000.00	1,400.00
10	RUST PROOFING	New	200.00	0.00
11	SPRAY PAINTING	New	2,000.00	1,400.00
Gross Labour Cost (\$\$)			5,650.00	3,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >