

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

ESTIMATE REPAIR LIST

HHTPClaims21-50

11 August 2021

AXA Insurance Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Department

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplemental work is not allowed
- Supplementary work must be approved and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCIDENT INVOLVING SMA 7211 C & SHD 9786 R ON 07/08/2021 ALONG SUP ROAD OF BEDOK NORTH ROAD TO BEDOK RESERVOIR ROAD AT ABOUT 0100 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SMA 7211 C
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No : ZYX102112281
Policy No : 5109921641-02-000144
Date of Accident : 07/08/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper / <i>re</i>		\$ 1,524.00
2	10	Rear Bumper Clip / <i>mc</i>	\$ 5.00	\$ 50.00
3	1	Rear Bumper Lower / <i>re</i>		\$ 1,073.10
4	1	Rear Bumper Lower Cover (Center) X <i>nn</i>		\$ 230.70
5	10	Rear Bumper Lower Clip / <i>mc</i>	\$ 5.00	\$ 50.00
6	2	Rear Bumper Retainer (LH/RH) X <i>nn</i>	\$ 293.40	\$ 586.80
7	1	Rear Reinforcement ?		\$ 964.50
				\$ 4,479.10
Less 20%				\$ (895.82)
				\$ 3,583.28
8	1	Reverse Sensor X <i>nn</i>	NETT	\$ 200.00
To change rear bumper, rear bumper lower, rear reinforcement. Knocking all area affected by accident				\$ 600.00 <i>200</i>
To perform wiring check				\$ 50.00 X <i>nn</i>
To spray rear bumper, rear reinforcement and all area affected by accident				\$ 600.00 <i>200</i>
7% GST				\$ 352.33
Total				\$ 5,385.61

2 Days. 4:30 pm

Gmo Qiang

82880282

25/8/21.

p/p. be for paint photos.

JL

Authorised by Claims Dept