



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS/FCI21008457/T1vf3e2 Date: 24/09/2021 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBS 6492A	Veh. Inspected	SBS 3928E
Policy No.		Coverage (\$)	0.00
Claim No.	D21002293MFBP	Excess (\$)	0.00
Assign From	MERINA CHIA	Assign Date	12/08/2021
2. Vehicle Particulars & Condition			
Make & Model	VOLVO B9TL	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	YV3S4P920FA170650	Colour	MULTI COLOUR
Odometer	488061 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	09/08/2021	Inspection Date	13/08/2021
Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	