



Re: E/3500/2021 - SBS3928E with GAS bus SBS6492A

Ang Chong Boon <angcb@sbstransit.com.sg>

Thu 8/12/2021 10:52 AM

Estimate for

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30750600	SIKA 711 WINDSCREEN SEALANT	3	\$21.00
30750043	MILLEN SCREEN PERIMETER RUBBER;FRT;LOWER	1	\$224.00
30750015	FRONT WINDSCREEN.LOW/S	1	\$944.00
(MO Number : BN2108001001)			Sub Total S\$: 1189.00

net ✓
net ✓
net ✓

- Parts cost: \$ 1189 ✓
- Contractor Labour cost: \$ 800 +gst ✓
- Workshop Labour cost: not required by surveyor x un
- Advertisement Cost: \$ 0
- Repair period: 3 days

- Tow Cost: \$ 0
- Loss of use: not required by surveyor x un
- Overheads: \$ 651.90 x un

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanpin 97695749
WP @ 13/8/21 @ 3:20pm
Using new parts
• 3 days