

Glockewerke

25 Kaki Bukit Road 4 #06-53/54 S417800

Hotline: +65 8112 6485

Email: glockewerke@outlook.com

ESTIMATE

Date: 12.08.2021

Vehicle No.: GBB8193P

Model: NISSAN NV200

JALYBAM20U0002849.

WW EXPRESS PTE LTD
27 JALAN RIMAU
SINGAPORE (418723)

TP Somp.

Denise.

PARTS AND LABOUR ASSESSMENT

DESCRIPTION OF PARTS	QTY	UNIT PRICE	TOTAL PRICE
FRONT BUMPER	1	\$ 620.00	\$ 620.00 ✓
REAR BUMPER	1	\$ 620.00	\$ 620.00 ✓
REAR TAIL LAMP LH	1	\$ 1,750.00	\$ 1,750.00 +
REAR TAIL LAMP RH	1	\$ 1,650.00	\$ 1,650.00 ✓ 1053.
REAR BUMPER REFLECTOR	2	\$ 80.00	\$ 160.00 ✓ 80.
FRONT GRILLE	1	\$ 450.00	\$ 450.00 ✓
FRONT LOTH HEADLAMP	2	\$ 435.00	\$ 870.00 ✓
FRONT BUMPER REINFORCEMENT BAR	1	\$ 610.00	\$ 610.00 ✓
AIRCON CONDENSER	1	\$ 210.00	\$ 210.00 ✓
RADIATOR	1	\$ 385.00	\$ 385.00 ✓
Sub-Total before discount:		\$ 7,325.00	
10% discount:		\$ 2,197.50	
Sub-Total after discount:		\$ 5,127.50	

less 10% 3089.70.

DESCRIPTION OF PARTS	QTY	UNIT PRICE	TOTAL PRICE
Rear Bumper Clips (Set)	1	\$30.00	\$30.00 ✓
Front Bumper Clips (Set)	1	\$30.00	\$30.00 ✓
PDC Sensor	2	\$100.00	\$200.00 ✓
Sub-Total before discount:		\$260.00	
0% discount:		\$0.00	
Sub-Total 2:		\$260.00	

260

LABOUR

Diagnose, replace and repair to rectify electrical system for proper function

: ~~\$120.00~~ 60

To provide workmanship labour to remove damage parts for assessment and to new bodyparts, repair, re-construct and re-adjust structure, body alignments and damaged consistent from the accident.

: ~~\$1,000.00~~ 600

To re-spray painting for change bodyparts, repair portion and where consistent from the accident

1160 : ~~\$1,200.00~~ 500

Labour Sub-Total: \$2,320.00

Parts and Labour Total: \$7,707.50

Adrian Lj
L/S 13/08/21

06 P. 77

total: 4509.70
L/S: 3.6K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: