

ASS. REC. BY: Tanjah

REF: CC4/ASM 21008469/Tips3

ASSIGNMENT

WE 2029 April

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 451K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKT16155 Yr Regn: 2009, Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish C.C. 1987

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 195354 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ST176J20W005001454

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12/8/210445

Survey held at AP Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ S. + RS. ____ SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Rep. Format: _____

Lump Sum / L.B.A. () _____

Estimation

Date
 Vehicle
 Make/Model
 Chassis No.

SKT 1615 J
 TOYOTA WISH
 JTDGJ20W005001454

No.	Description	Unit	Unit Price	Amount
	Parts Replacment			
1	BONNET <i>X</i>	1	\$	-
2	BONNET LOGO - TOYOTA <i>X</i>	1	\$	-
3	BONNET LOCK <i>X</i>	1	\$	-
4	BONNET LOCK CATCH <i>X</i>	1	\$	-
5	HEADLAMP L+R <i>LH X RH</i>	2	\$	-
6	HEADLAMP BRACKET L+R <i>LH X RH</i>	2	\$	-
7	FRONT GRILLE ASSY <i>X</i>	1	\$	-
8	FRONT BUMPER <i>de</i>	1	\$	-
9	FRONT BUMPER RETAINER RH <i>nei</i>	1	\$	-
10	FRONT BUMPER REINFORCEMENT BAR <i>X</i>	1	\$	-
11	FRONT BUMPER SPONGE <i>nei</i>	1	\$	-
12	FRONT BUMPER FOG LAMP RH <i>nei</i>	1	\$	-
13	FRONT BUMPER FOG LAMP GARNISH RH <i>nei</i>	1	\$	-
14	FRONT FENDER RH <i>bt</i>	1	\$	-
15	FRONT FENDER SIGNAL LAMP RH <i>X</i>	1	\$	-
16	FRONT FENDER COWLING RH <i>fn</i>	1	\$	-
17	FRONT SUPPORT PANEL <i>X</i>	1	\$	-
18	FRONT SUPPORT PANEL TOP GARNISH <i>X</i>	1	\$	-
19	FRONT ABSORBER RH <i>X</i>	1	\$	-
20	FRONT LOWER ARM RH <i>X</i>	1	\$	-
21	FRONT KNUCKLE ARM RH <i>?</i>	1	\$	-
22	FRONT KNUCKLE BEARING HUB RH <i>?</i>	1	\$	-
23	FRONT BEARING HUB RH <i>X</i>	1	\$	-
24	FRONT TIE ROD RH <i>X</i>	1	\$	-
25	FRONT TIE ROD END RH <i>X</i>	1	\$	-
26	FRONT DRIVE SHAFT RH <i>X</i>	1	\$	-
27	FRONT STEERING RACK AND PINION ASSY <i>X</i>	1	\$	-
28	FRONT STABILIZER LINK RH <i>X</i>	1	\$	-
	Front Door RH <i>RX</i>		Total	\$ 10,993.05
	Front Door Side Mirror Assy RH <i>? plus fo</i>		Less 25%	\$ 2,748.26
	Front Door Side Mirror Cover RH <i>RX</i>		Total	\$ 8,244.79
	Wiper washer Tank <i>de</i>			

	S/Nett Items				
1	FRONT NUMBER PLATE <i>X</i>	1	100	\$ <i>X</i>	100.00
2	FRONT BUMPER CLIPS	1	100	\$ <i>30</i>	100.00
3	FRONT FENDER COWLING CLIPS	1	100	\$ <i>10</i>	100.00

4	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1	100	\$	100.00
5	FRONT RIM RH	1	2500	\$ 600 ^{cut}	2,500.00
6	FRONT TYRE RH	1	800	\$	800.00
	Total			\$	3,700.00

	LABOUR				
1	PANEL BEATING ON AFFECTED AREAS	1	1400	\$	1,400.00
2	SPRAY PAINT ON AFFECTED AREAS	1	1400	\$	1,400.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	1	150	\$	150.00
4	TO CHECK WHEEL ALIGNMENT AND ADJUST	1	250	\$	250.00
5	TO RNR UNDERCARRIAGE	1	250	\$	250.00
6	TO CHECK WHEEL BALANCING	1	250	\$	250.00
7	TO UNLOAD AND UPHOISTERY	1	400	\$	400.00
8	TO CHECK WATER LEAK	1	150	\$	150.00
9	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	1	300	\$	300.00
10	TO RNR FRONT RADIATOR	1	250	\$	250.00
11	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	1	600	\$	600.00
12	TO PERFORM RUST PROOFING	1	400	\$	400.00
13	TO RNR HORN AND TEST FUNCTION	1	150	\$	150.00

Total Labour \$ **5,950.00**

Parts Replacement Amount \$ **9,444.79**

Total Amount \$ **14,444.79**

Tasfih 97495749
 WP 12/8/21 @ 445
 L/S Resurvey after repair
 Tasfih c/hk auto.com
 4 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 981E

Vehicle Details

Vehicle No.: SKT1615J
Vehicle to be Exported: No
Intended Deregistration Date: 31 Aug 2021
Vehicle Make: TOYOTA
Vehicle Model: WISH 2.0 AUTO
Primary Colour: Green
Manufacturing Year: 2009
Engine No.: 3ZRA414656
Chassis No.: JTDGJ20W005001454
Maximum Power Output: 106.0 kW (142 bhp)
Open Market Value: \$22,003.00
Original Registration Date: 24 Nov 2009
First Registration Date: 24 Nov 2009
Transfer Count: 4
Actual ARF Paid: \$22,003.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2029
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
PQP Paid: \$35,411.00
COE Rebate Amount: \$27,148.00
Total Rebate Amount: \$27,148.00

The information contained herein is correct as at 11 Aug 2021

OK