

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJM 3/46G

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

TEL: 64193000

ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES2190764/YISHUN

Date: 13 Aug 2021

Policy No: 5105793614-02

Veh Reg No: SJM3146G

Make/Model: MITSUBISHI LANCER
1.6 M

Chassis No: JMYSNCS3A9U002022

Engine No: 4G18JY9868

Reg. Date: 29/12/2008

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 10/08/2021

TP Veh Reg No: GBH2204A

Not Notarized

11 Pgs 84950/1

Survey After Rain

7 days

Estimate Repair Cost to Vehicle No :SJM3146G

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 REAR BUMPER 697	697.00	1 PC	697.00	✓
2 REAR BUMPER LOWER SKIRT	668.00	1 PC	668.00	✓
3 REAR BUMPER SIDE RETAINERS	101.00	2 PCS	202.00	✓
4 REAR BUMPER CENTRE INNER BEAM 209	209.00	1 PC	209.00	✓
5 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
6 REAR BOOT 593	593.00	1 PC	593.00	✓
7 REAR BOOT INNER LOCK	69.00	1 PC	69.00	✓
8 REAR BOOT INNER RUBBER	175.00	1 PC	175.00	50/50 84.50/50
9 REAR BOOT LOGO	55.00	1 PC	55.00	✓
10 REAR BOOT EMBLEM (MITSUBISHI)	56.00	1 PC	56.00	✓
11 REAR BOOT EMBLEM (GLX)	35.00	1 PC	35.00	✓
12 REAR NUMBER PLATE GARNISH	221.00	1 PC	221.00	✓
13 TAILLAMPS 0421 0456 0456	421.00	2 PCS	842.00	✓
14 TAILLAMP INNER CLIPS	5.00	6 PCS	30.00	✓
15 REAR CENTRE PANEL 474	495.00	1 PC	495.00	✓
16 REAR CENTRE PANEL INNER TOP GARNISH	176.00	1 PC	176.00	✓
17 REAR EXHAUST PIPE	439.00	1 PC	439.00	✓
			4,983.00	
		Less 10%	498.30	4,484.70
Special Net				
18 REVERSE SENSOR	200.00	1 SET	200.00	✓
			200.00	200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ASSIGNMENT

Veh No:

Type: M Car / M Cycle

SJM 3146G

Yr Regn:

12, 08

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 10/08/2021

TP Veh Reg No: GBH2204A

Estimate No: ES2190764/YISHUN

Date: 13 Aug 2021

Policy No: 5105793614-02

Veh Reg No: SJM3146G

Make/Model: MITSUBISHI LANCER
1.6 M

Chassis No: JMYSNCS3A9U002022

Engine No: 4G18JY9868

Reg. Date: 29/12/2008

Estimate Repair Cost to Vehicle No :SJM3146G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
19 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, REAR BOOT & SPOILER, LOWER SKIRT, TO CUT, WELD & RENEW REAR END PANEL, KNOCK & REPAIR REAR BOTH FENDERS, REAR SPARE TYRE COMPARTMENT, STRAIGHTEN REAR RH CHASSIS & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1080
20 REMOVE & REFIX REVERSE, EXHAUST & CHECK SYSTEM	60.00	1 LA	60.00	✓
21 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, REAR BOOT, REAR BUMPER, REAR LOWER SPOILER & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
22 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,320.00	2,320.00
			Total	S\$ 7,004.70
			Add GST @ 7%	490.33
			Total Amount Payable	S\$ 7,495.03

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE