

REF: C12 / 210084741Ku

ASSIGNMENT

Veh No: SLL 3551B Yr Regn: 02, 17
M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime MoverCO. REG. NO: 199402370D
GST NO: M2-0123250-3**K. Kim Hin** AUTO PTE LTD**金興(龔)汽車私人有限公司**160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 31958

Vehicle Insured : SJF 914 M
Accident Date : 10-Aug-2021*Not Authorized* Date : 12-Aug-2021

Our Ref : 021323 (CHINA) / QUEK

11 Days 8, 18, 1

PAGE : 1

BUKIT BATOK DRIVING CENTER LTD
Singapore*Penalty After Repair**5 days*ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5 VTIR M/T ABS(2017) SLL3551B
=====

1 pc rear bumper		Ry 492.00	✓
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 30.00	old 60.00	LT
2 pcs rear bumper side lower garnish (LH/RH)	@ S\$ 45.00	Rn 90.00	X
10 pcs rear bumper clips	@ S\$ 3.90	Rn 39.00	✓
1 pc rear end panel		Bn 352.20	✓
1 pc rear end panel top garnish		Dr 100.00	✓
1 pc o/s tail lamp		LT 237.00	✓
1 pc spare tyre sponge compartment		CM 680.00	✓
1 pc tailgate		Ry 769.30	✓
1 pc tailgate weatherstrip		Dr 122.30	50% 61.155w
1 pc tailgate lock		R 280.00	X
1 pc tailgate "JAZZ" emblem		Rn 38.00	✓
1 pc tailgate outer chrome		Rn 195.60	X
1 pc tailgate inner trimboard		Sn 189.80	X
1 pc tailgate glass moulding		Rn 150.00	✓
1 pc tailgate inner handle pocket		Dr 63.40	✓
<i>1 pc Rear Bumper</i>	<i>34.40</i>		✓ CM
		3,858.60	
	Less 20% :	-771.72	
		3,086.88	

- 1 pc rear bumper "L" plate bracket
2 pcs tailgate "8" & "0" reflective @ S\$ 10.00
sticker
1 pc tailgate "THANK YOU FOR YOUR
PATIENCE"
1 pc tailgate glass sealant
1 pc tailgate glass damping seal

Rn 60.00 sn X
Rn 20.00 sn ✓
Rn 150.00 sn ✓
Rn 40.00 sn ✓
Rn 20.00 sn ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(興)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SJF 914 M
Our Ref : 021323

Page : 2
No. : 31958

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.	600 680.00
To remove and renew rear windscreen glass and conduct water leak test.	120.00 ✓
To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	180.00 600
To apply undersealing	80.00 600
To transfer tailgate's fittings	80.00 600
To putty and respray on affected portions.	780.00 600
To focus taillamps. To check rear wiring and lighting operation.	30.00 200
Total :	----- S\$ 5,326.88 =====

Singapore Dollars Five Thousand Three Hundred
and Twenty Six and Cents Eighty Eight Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.