



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2108687

INV Date 17/12/2021

Reference CC4/LPC21008480/Ugs3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. FBS 2290S

Insured Veh. SML 6366M

Claim No. 20/21/21/VP05/024752

Policy No.

Accident Date 07/07/2021

Inspection Date 13/08/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                  |                 |                                                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                      |                                                                                  |                 | Ref: CC4/LPC21008480/Ugs3q2<br>Date: 17/12/2021<br>Code: LPC2 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                  |                 |                                                               |  |
| Insured Veh.                                                                                                                           | SML 6366M                                                                        | Veh. Inspected  | FBS 2290S                                                     |  |
| Policy No.                                                                                                                             |                                                                                  | Coverage (\$)   | 0.00                                                          |  |
| Claim No.                                                                                                                              | 20/21/21/VP05/024752                                                             | Excess (\$)     | 0.00                                                          |  |
| Assign From                                                                                                                            | ONG LI LI                                                                        | Assign Date     | 12/08/2021                                                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                  |                 |                                                               |  |
| Make & Model                                                                                                                           | YAMAHA AEROX 155                                                                 | c.c             | 155                                                           |  |
| Engine No.                                                                                                                             | HIDDEN                                                                           | Year of Reg.    | 2021                                                          |  |
| Chassis No.                                                                                                                            | MH3SG6420LJ001903                                                                | Colour          | BLACK                                                         |  |
| Odometer                                                                                                                               | 8198 KM                                                                          | Steering        | AFFECTED                                                      |  |
| Brakes                                                                                                                                 | IN ORDER                                                                         | Modification    | SPORTS RIM                                                    |  |
| General                                                                                                                                | FAIR                                                                             |                 |                                                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                  |                 |                                                               |  |
|                                                                                                                                        | Size                                                                             | Make            | Balance                                                       |  |
| R/H Front Tyre                                                                                                                         | 110-80-14                                                                        | MICHELIN        | 7 mm                                                          |  |
| L/H Front Tyre                                                                                                                         |                                                                                  |                 | mm                                                            |  |
| R/H Rear Tyre                                                                                                                          | 140-70-14                                                                        | MICHELIN        | 7 mm                                                          |  |
| L/H Rear Tyre                                                                                                                          |                                                                                  |                 | mm                                                            |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                  |                 |                                                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY.<br>DAMAGES SEE DETAILS.                                           |                                                                                  |                 |                                                               |  |
| <b>5. General Information</b>                                                                                                          |                                                                                  |                 |                                                               |  |
| Accident Date                                                                                                                          | 07/07/2021                                                                       | Inspection Date | 13/08/2021                                                    |  |
| Survey held at                                                                                                                         | F.T. FASTTRACK<br>25 KAKI BUKIT ROAD 4<br>#01-77 SYNERGY @KB<br>SINGAPORE 417800 |                 |                                                               |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                  |                 |                                                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                  |                 |                                                               |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                  |                 |                                                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                  |                 | 4 Working Days                                                |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 2290S

| Qty | Description of Parts               | Condition                      | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------|--------------------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b> |                                |                           |                   |
| 1   | HEADLAMP                           | SCRATCHED                      | 499.00                    | 499.00            |
| 1   | FRONT COVER                        | CUT / CRACKED                  | 155.00                    | 155.00            |
| 1   | FRONT COVER PANEL TOP              | CRACKED                        | 68.00                     | 68.00             |
| 2   | COVER (LH) & (RH) OUTER @\$155.00  | N/S CUT                        | 310.00                    | 155.00            |
| 2   | COVER (LH) & (RH) INNER @\$68.00   | N/S CUT                        | 136.00                    | 68.00             |
| 1   | MIRROR (RH)                        | CUT                            | 38.00                     | 38.00             |
| 1   | FRONT FENDER UPPER                 | TO REPAIR SEE LABOUR           | 68.00                     | -                 |
| 1   | FRONT FENDER LOWER                 | SCRATCHED                      | 72.00                     | 72.00             |
| 2   | FORK (LH) & (RH) @\$399.00         | N/S BENT                       | 798.00                    | 399.00            |
| 1   | UNDER BRACKET                      | BENT                           | 295.00                    | 295.00            |
| 1   | FRONT WHEEL RIM                    | TO REPAIR SEE LABOUR           | 335.00                    | -                 |
| 1   | HANDLE BAR                         | BENT                           | 175.00                    | 175.00            |
| 1   | BALANCER (LH)                      | MISSING                        | 25.00                     | 25.00             |
| 2   | BRAKE LEVER (RH) & (LH) @\$38.00   | N/S DAMAGED                    | 76.00                     | 38.00             |
| 2   | MIRROR (RH) & (LH) @\$48.00        | N/S BROKEN/ O/S REPEATED       | 96.00                     | 48.00             |
| 1   | MASTER PUMP                        | CUT                            | 195.00                    | 195.00            |
| 1   | FRONT HANDLE COVER                 | NOT NECESSARY                  | 65.00                     | -                 |
| 1   | METER PANEL                        | NOT NECESSARY                  | 58.00                     | -                 |
| 1   | FOOT STEP UPER (LH)                | CUT                            | 125.00                    | 125.00            |
| 1   | LOWER COVER (LH)                   | CUT                            | 125.00                    | 125.00            |
| 1   | SIDE STAND                         | TO REPAIR SEE LABOUR           | 68.00                     | -                 |
| 1   | MAIN STAND                         | CUT                            | 190.00                    | 190.00            |
| 1   | REAR FOOTREST (LH)                 | CUT                            | 58.00                     | 58.00             |
| 1   | AIR BOX COVER                      | SCRATCHED                      | 70.00                     | 70.00             |
| 1   | BELT COVER                         | SCRATCHED                      | 175.00                    | 175.00            |
| 2   | TAIL COVER (LH) & (RH) @\$75.00    | N/S CUT                        | 150.00                    | 75.00             |
| 1   | FOOT STEP (LH)                     | DISTORTED                      | 125.00                    | 125.00            |
| 1   | RADIATOR COVER (SCRATCHED)         | NOT CONSISTENT WITH THE IMPACT | 65.00                     | -                 |

Report Ref No. CC4/LPC21008480/Ugs3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                | Description of Parts                                                                                                       | Condition                      | Estimate By Workshop (\$) | Our Adjusted (\$) |
|--------------------|----------------------------------------------------------------------------------------------------------------------------|--------------------------------|---------------------------|-------------------|
| 1                  | EXHAUST PIPE                                                                                                               | NOT NECESSARY                  | 535.00                    | -                 |
| 1                  | EXHAUST COVER (SCRATCHED)                                                                                                  | NOT CONSISTENT WITH THE IMPACT | 102.00                    | -                 |
| 2                  | TAIL COVER PANEL (LH) & (RH) @\$68.00                                                                                      | TO REPAIR SEE LABOUR           | 136.00                    | -                 |
| 1                  | TOP BOX -ALUMIUM                                                                                                           | CUT                            | 390.00                    | 350.00            |
| 1                  | TOP BOX BACK                                                                                                               | BENT                           | 105.00                    | 105.00            |
| 1                  | FRONT NO PLATE                                                                                                             | SERVICEABLE                    | 20.00                     | -                 |
|                    | LESS 10% DISCOUNT                                                                                                          |                                | -590.30                   | -362.80           |
|                    |                                                                                                                            |                                | 5,312.70                  | 3,265.20          |
|                    | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                           |                                |                           |                   |
| 1                  | ERP IU UNIT (SN)                                                                                                           | CUT                            | 160.00                    | 160.00            |
|                    |                                                                                                                            |                                | 160.00                    | 160.00            |
|                    | <b><u>LABOUR</u></b>                                                                                                       |                                |                           |                   |
|                    | TRANSPORT FEE .                                                                                                            |                                | 70.00                     | 70.00             |
|                    | CHASSIS REPAIR .                                                                                                           | NOT NECESSARY                  | 280.00                    | -                 |
|                    | LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF FRONT FENDER UPPER ,FRONT WHEEL RIM ,SIDE STAND AND TAIL COVER PANEL (LH) & (RH). |                                | 350.00                    | 300.00            |
|                    |                                                                                                                            |                                | 700.00                    | 370.00            |
| <b>GRAND TOTAL</b> |                                                                                                                            |                                | <b>6,172.70</b>           | <b>3,795.20</b>   |

|                                                                                 |  |  |                 |
|---------------------------------------------------------------------------------|--|--|-----------------|
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS<br/>(TO ITS PRE-ACCIDENT CONDITION)</b> |  |  | <b>3,000.00</b> |
|---------------------------------------------------------------------------------|--|--|-----------------|

Report Ref No. CC4/LPC21008480/Ugs3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. FBS 2290S

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBS 2290S

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBS 2290S

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

