



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2107930
3 ANSON ROAD #16-00	INV Date	18/11/2021
SPRINGLEAF TOWER	Reference	CC6/CTI21008483/Ara3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	GBL 249M
Insured Veh.	GBF 7421S
Claim No.	SNM21D204479/LKKDS
Policy No.	DMCVSNW00110502000
Accident Date	11/08/2021
Inspection Date	12/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI21008483/Ara3q2 Date: 18/11/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 7421S	Veh. Inspected	GBL 249M
Policy No.	DMCVSNW00110502000	Coverage (\$)	0.00
Claim No.	SNM21D204479/LKKDS	Excess (\$)	0.00
Assign From		Assign Date	12/08/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE	c.c	2754
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	GDH2012016665	Colour	WHITE
Odometer	7039 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195/80 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195/80 R15	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/08/2021	Inspection Date	12/08/2021
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 249M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	656.20	656.20
2	REAR BUMPER O/S & N/S RETAINER	NECESSARY	182.70	182.70
1	REAR END PANEL OUTER	DENTED	594.60	594.60
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	613.50	-
1	REAR TAIL-GATE	DENTED	2,425.90	2,150.00
1	REAR TAIL-GATE WEATHERSTRIP	NOT NECESSARY	420.00	-
1	REAR TAIL-GATE EMBLEM	NECESSARY	82.00	82.00
1	REAR TAIL-GATE LOCK	DAMAGED	392.00	282.00
1	REAR TAIL-GATE CATCH	NOT NECESSARY	140.60	-
1	REAR BUMPER REINFORCEMENT (ADDITIONAL)	DENTED	265.00	265.00
4	REAR BUMPER LOWER BRACKET @\$29.00 (ADDITIONAL)	BENT	116.00	116.00
	LESS 25% DISCOUNT		-1,472.13	-1,082.13
			4,416.37	3,246.37
<u>SPECIAL NETT ITEMS</u>				
2	REAR BUMPER SCREW (SN)	NOT NECESSARY	20.00	-
10	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	120.00	120.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	REAR TAIL-GATE 70KM/PH EMBLEM (SN)	NECESSARY	15.00	15.00
1	REAR TOYOTA HIACE EMBLEM (SN)	NECESSARY	60.00	60.00
1	REAR REG NO.PLATE (SN)	NOT NECESSARY	35.00	-
1	REAR REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
			610.00	485.00
<u>LABOUR</u>				
	TO REMOVE AND REPLACE REAR DAMAGED PARTS ,STRAIGHTEN & WELDING .INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER .		1,000.00	800.00
	TO SPRAY PAINTING.		800.00	500.00
	TO REMOVE & REFIT REAR WINDSCREEN.		140.00	120.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING .		100.00	30.00
	TO RE-SEAL ANTI-RUST.		150.00	60.00
			2,190.00	1,510.00
GRAND TOTAL			7,216.37	5,241.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CC6/CT121008483/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 249M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBL 249M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

