

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 11.08.2021

Time: 15:44:36

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305482332
 REGN NO : SHC7253E
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 25.08.2016
 DATE/TIME IN : 11.08.2021 12:40
 ACCIDENT DATE : 11.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A BUMPER FRT COVER+ 1 1,052.20 20.00 841.76 *Rp*0002 04-01-0103-2164-A GRILLE ASSY-RADIATOR+ 1 1,480.00 20.00 1,184.00 *Ang ✓*0003 04-01-0103-2175-G SYMBOL MARK-H 1 129.50 20.00 103.60 *Ang ✓*0004 04-01-0101-0111-G BUMPER COVER CLIP 10 22.00 20.00 17.60 *Ang ✓*0005 28-01-0103-2028-A VEHICLE NUMBER PLATE FRON 1 N 50.00 10.00 45.00 *Ang ✓*

SUB-TOTAL : 2,191.96

JOB NATURE

0000 PB PANEL BEATING 300.00 *280*0001 SP SPRAYPAINT CHARGE 300.00 *250*0002 17-01 CHECK ALL LIGHTING 50.00 *30*

SUB-TOTAL : 650.00

Tanpin 17415719
WP' 11/8/21 @ 430 pm
CLB Resurvey after repair
2 days
Tanpin C/Management

1631.50
20% - 1305.20.
50
10% - 45
1350.20.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pending - GLA Report