



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3464J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,789.90	-
1	REAR DOOR OUTER MOULDING	TO REPAIR SEE LABOUR	125.30	-
	LESS 20% DISCOUNT		-736.70	-
			2,946.80	-
SPECIAL NETT ITEMS				
1	REAR DOOR COMFORTDELGRO & APPS STICKER RH (SN)	NECESSARY	80.00	80.00
			80.00	80.00
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER RH,REAR DOOR RH AND REAR DOOR OUTER MOULDING.		1,050.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	REMOVE & REFIX CUSHION & UPHOLSTERY REAR.	NOT NECESSARY	120.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
			1,950.00	850.00
GRAND TOTAL			4,976.80	930.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				930.00

Report Ref No. NS/INC21008495/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.