

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21008497/KGA3Q2**Date:** 29/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993714
Claimant Vehicle No :	SJW6569Y	Insured Vehicle No :	SLB2073Z
Date of Loss:	22/07/2021	Nature of Claim:	TP
		Claim No:	6288684581SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW6569Y	Engine No:	HIDDEN
Make & Model:	MERCEDES-BENZ S300L, 3.0 (A)	Chassis No:	WDD2211542A311888
Reg. Date:	01/04/2010 (Man. Year: 2010)	Odometer:	118889 km
Colour:	Black		
Engine Capacity:	2997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R18	Rear Tyre Size:	255/45 R18
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	13/08/2021	Chew Goon Motor (AMK)
Date Inspected:	13/08/2021 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	7.0 days	Singapore 568047

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$90,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER BRACKETS	* Check	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	* Check	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	* Check	0.00 F	*- F
6	1		*REAR BUMPER CENTER CORE	* Check	0.00 F	*- F
7	2		*REAR BUMPER SIDE MOULDINGS	Necessary	0.00 F	*- F
8	1		*REAR BUMPER TOP BEAM	* Check	0.00 F	*- F
9	2		*REAR BUMPER REVERSE SENSOR	Scratched	0.00 F	*- F
10	6		*REAR BUMPER REVERSE SENSOR HOLDERS	* Check	0.00 F	*- F
11	2		*REAR BUMPER TOP RETAINERS	Serviceable	0.00 F	*- F
12	1		*INNER BOOT SENSOR	* Check	0.00 F	*- F
13	1		*BOOT	Bent	0.00 F	*- F
14	1		*BOOT EMBLEM	Necessary	0.00 F	*- F
15	1		*BOOT BADGE S300	Necessary	0.00 F	*- F
16	1		*BOOT BADGE L	Necessary	0.00 F	*- F
17	1		*BOOT BADGE 7G-TRONIC	Necessary	0.00 F	*- F
18	1		*BOOT BADGE C&C	Necessary	0.00 F	*- F
19	1		*BOOT LOCK	Dented	0.00 F	*- F
20	8		*BOOT TRIM BOARD CLIPS	Not Necessary	0.00 F	*- F
21	2		*TAILLAMPS	Cracked	0.00 F	*- F
22	2		*TAILLAMP GASKETS	Necessary	0.00 F	*- F
23	1		*REAR FENDER GUTTER GARNISH RH	Cracked	0.00 F	*- F
24	1		*END PANEL	* Check	0.00 F	*- F
25	1		*END PANEL GARNISH	Mtg Cracked	0.00 F	*- F
26	1		*GRILLE	Dented	0.00 F	*- F
27	1		*FRONT BUMPER	Mtg Cracked	0.00 F	*- F
28	1		*FRONT BUMPER CLIPS	Necessary	0.00 F	*- F
29	1		*FRONT BUMPER SPONGE	Serviceable	0.00 F	*- F
30	1		*FRONT BUMPER REINFORCEMENT	Repair	0.00 F	*- F
31	2		*FRONT BUMPER SENSORS	* Check	0.00 F	*- F
32	6		*FRONT BUMPER SENSOR HOLDERS	* Check	0.00 F	*- F
33	1		*FRONT BUMPER LOWER MOULDING	Necessary	0.00 F	*- F
34	2		*FRONT BUMPER LOWER SIDE MOULDINGS	Necessary	0.00 F	*- F
35	1		*FRONT BUMPER NUMBER PLATE HOUSING	Mtg Cracked	0.00 F	*- F
36	1		*HEADLAMPS	N/S Mtg Cracked	0.00 F	*- F
37	1		*SUPPORT PANEL SIDE AIR GUIDE	Serviceable	0.00 F	*- F
38	1		*DRIVERS SEAT HEADREST	* Check	0.00 F	*- F
39	1		*FRONT NUMBER PLATE	Bent	0.00 F	*- F
40	1		*BOOT WEATHERSTRIP	Cut	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) **0.00** **0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >