MFORT TRANSPORTATION PTE LTD

EPAIR ESTIMATE

Vehicle No.: SHD8825T

Make : HYUNDAI Model

Date: 12/08/21

odel	: IONIQ(G3)	lr	surance: NTUC	<i>L</i> ()	
Qty	the state of the s		MVA: MS. LOKE YY		
	Parts Description / Labour	Туре	Unit Price	Amount	
	1 REAR FENDER RH		A LATE	1 /0 \$1,768.30	
	1 REAR WHEEL HUB CAP RH		j.	art \$346.40	
	1 RR BUMPER COVER			RY \$459.40	
	1 REAR BUMPER CLIPS			M \$22.00	
	SUB TOTAL		1 20		
	LESS 20%		2136.10	\$2,596.10	
	DISCOUNTED TOTAL		1209 Sh	\$519.22	
	SIGGOUNTED TOTAL		2136.70	\$2,076.88	
	1 REAR FENDER ADVERTISEMENT LOGO RH		w	4 \$100.00	
			0 = 0	\$100.00	
	Labour Charge				
	PANEL BEATING	1	<-		
	SPRAY PAINTING CHARGE)	\$1,050.00	
	WIRING CHARGE	- 1	5	\$700.00	
	TUFF KOTE			AUX \$60.00	
	REMOVE & REFIX CUSHION & UPHOLSTERY REAR		1085	M× \$60.00	
			(0.0	GO \$150.00	
	TOTAL LABOUR		(085 2894-36 el 69 2300 3 days.	£2,020,00	
		l	11187270	\$2,020.00	
	ESTIMATE TOTAL	1	0159 050	£4.400.00	
			Zoleus.	\$4,196.88	
1	l estimate based on a visual inspection of the above vehicle. The		- 1		

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tauphin 97415749 WP' 1218/21 2330/2 W US Mony Myrepair Juphine Manhain

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Conipany

Acknowledged by Repairer

Signature:

Date: