



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|---|----------------------------|--------------|
| TAN KOK QUAN PARTNERSHIP 1 WALLICH STREET #07-02 GUOCO TOWERSINGAPORE 078881 | | | Ref: CS/LAW21008499/Uuf3e2 | |
| | | | Date: 21/10/2021 | |
| | | | Code: L021 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION) | | | | |
| | Insured Veh. | SHC 6191G | Veh. Inspected | SMP 1911B |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | (V)TWK/DAQ/pkf/0522.21 | Excess (\$) | 0.00 |
| | Assign From | TEO WENG KIE | Assign Date | 02/08/2021 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | MASERATI GRANTURISMO CAMBIOCORSA (A) | c.c | 4691 |
| | Engine No. | HIDDEN | Year of Reg. | 2010 |
| | Chassis No. | ZAMHH45C000053548 | Colour | GREY / BLACK |
| | Odometer | 107114 KM | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 245/35Z R20 | TOURADOR | 7 mm |
| | L/H Front Tyre | 245/35Z R20 | TOURADOR | 7 mm |
| | R/H Rear Tyre | 285/30 R20 | BRIDGESTONE | 7 mm |
| | L/H Rear Tyre | 285/30 R20 | BRIDGESTONE | 7 mm |
| 4. Description of Damages | | | | |
| | THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS. | | | |
| 5. General Information | | | | |
| | Accident Date | 17/02/2020 | Inspection Date | 01/09/2021 |
| | Survey held at | Block 5 Defu Lane 10, #01-582 | | |
| | Repairer | HENG MOTOR SERVICES | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: | | 5 Working Days | |