

ASSIGNMENT

From:

Date:

Veh No:

Yr Regn:

Estimated Cost:

Type:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

BK.19771.20.P

Claims No.

(V)TWK/DAQ/pkf/0522.21

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 5

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

2461

Veh No:

Yr Regn:

Type:

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond:

Steering:

Brake:

Modi:

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

see u4f1 / 31-10-2029

priority report photo page 8/24 headlamp lower RH N/A photo 1541

18/10/21 submit L/S \$15,000 5 days.
(RED \$9000; 38%)

Date/Time, File Pass to?



: Preli. Report

1) 18/10 TYPIST



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format: TP

Lump Sum / L.S. (\$ 15000

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

TOTAL



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No.	TP/0018/20	Date of Report	: 17 March 20
To :	Hu Shunrong	Date of Request	: 21 February 20
		Report requested by	: Hu Shunrong
229, Wak Hassan Drive		Date of Accident	: 17 February 20
Singapore 757544		Date of Inspection	: 21 February 20
		Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SMP 1911 B	Odometer Reading	: 76,166 km
Make	: Maserati	Carrying Capacity	: 4
Model	: Grand Turismo (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2010	Air-Conditioner	: Yes
Colour	: Black	Wing Mirror	: Yes
Engine Capacity	: 4,691 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: ZAMHH45C000053548	Others	: Nil

TYRE CONDITION

Front Left	: 5mm	Front Right	: 5mm
Make	: Michelin	Make	: Michelin
Rear Left	: 5mm	Rear Right	: 5mm
Make	: Michelin	Make	: Michelin
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Nil	Spare Tyre	: Nil
--------------	-------	------------	-------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	29,749.61	28,074.41
Labour Charges :	2,390.00	1,410.00
Paint Work :	1,000.00	700.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	33,139.61	30,184.41

Reduction (S \$) : 9,139.61

Recommended Reserve (S \$) : 24,000.00 (Lump Sum)

Estimated Normal Period of Repairs : 7 working days

S-day.

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at Heng Motor Services Pte Ltd, Block 5, Defu Lane, #01-582, Singapore 539186. Follow-up inspection has been conducted.

Point of Impact

At the LH front portion (LH front roadwheel was also affected).

Damages

The front bumper, LH front fender, LH headlamp assembly, LH front wheel, LH front undercarriage parts, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$30,184.41

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$24,000.00


Pre-accident market value : About \$130,000.00

COE and PARF rebate : \$99,764.00

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES


JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser


LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SMP 1911 B Maserati Grand Turismo (A)

TP/0018/20

Workshop : Heng Motor Services Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist.%	Our Recommendation (S S)	Dist.%
To Supply :					
1pc. Front bumper	Dented / Cracked	5,373.00	10	de/fora 5,373.00	10
1set. Front bumper fasteners	Necessary	70.00	10	new 70.00	10
1pc. Front bumper centre emblem	Necessary	78.54	10	new 78.54	10
1pc. Front bumper LH grille	Refit	698.00	10	refit --	10
1pc. Front LH fender	Dented / Distorted	6,220.00	10	R 6,220.00	10
1pc. Front LH fender emblem	Necessary	45.25	10	new 45.25	10
1pc. LH headlamp	Defaced / Cut	4,331.00	10	polish 4,331.00	10
1pc. LH front sport rim (original)	Grazed / Cut	2,558.00	10	cut 2,558.00	10
1pc. LH front knuckle arm	Bent 2845	2,660.00	10	dent 2,660.00	10
1pc. LH front lower arm	Bent	2,063.00	10	dent 2,063.00	10
1pc. LH front upper arm	Bent 2000	2,298.00	10	dent 2,298.00	10
1pc. LH front shock absorber	Bent 2815	3,713.00	10	dent 3,713.00	10
1pc. LH front shock absorber top mounting	Refit	330.00	10	refit --	10
1pc. LH front wheel bearing	Warped 1486	1,784.00	10	new 1,784.00	10
Sub-Total :-		32,221.79		31,193.79	
Total Discount :-		3,222.18		3,119.38	
		28,999.61		28,074.41	
Special Nett Items :-					
1pc. LH front tyre	Refit	750.00		refit --	
Total For Parts :-		29,749.61		28,074.41	
Labour Charges :					
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re-position & re-align, replacement of parts to the original position including adjustment.		1,500.00		900.00	800
Spray rust coating on the replaced & repaired panels.		60.00	11	--	X
Check wiring & lighting system for proper function.		80.00		50.00	40
Remove, check, re-install & replace H front undercarriage parts to assist repairs.		550.00		300.00	200
Conduct test drive & re-adjust wheel alignment system (before and after).		200.00		160.00	120
Spray Painting :					

Vehicle No : SMP 1911 B Maserati Grand Turismo (A)

TP/0018/20

Workshop : Heng Motor Services Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
To putty & spray repaired & replaced body panels.		1,000.00		700.00	500
Grand Total :-		33,139.61		30,184.41	

Surveyed By : Lawrence Ng

P-19033.78

L-1060