

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121008503/AUF3N2**Date:** 19/11/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : GBF7005K **Insured Vehicle No :** YN2662G

Date of Loss: 06/08/2021 Nature of Claim: TP Claim No: CDMCG21001461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF7005K**

Make & Model: NISSAN NV200, 1.6 DX-2 (A) Engine No: HR16079543D

Reg. Date: 15/02/2017 (Man. Year: 2016) Chassis No: VM20102518

Colour: Black Odometer: 52257 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70R14C Rear Tyre Size: 175/70R14C

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,302.00	1,624.50	1,677.50	50.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,120.00	410.00	26.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,832.00	2,744.50	2,087.50	43.20
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	4,832.00	2,200.00	2,632.00	54.47

INSPECTION

Date of Assignment: 13/08/2021

Date Inspected: 12/08/2021 Inspected At: Best Solution Autocare Pte Ltd (HQ)
53 UBI AVE 1 #03-01 PAYA UBI INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Nov 2021)	
Parts:	N/A	NISSAN NV200 1.6 DX-2 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7005K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S FRONT DOOR	Dented	1,985.00 F	*1,350.00 FL
2	1		*O/S FRONT FENDER	Repair	668.00 F	*- FL
3	1		*O/S FRONT SIDE MIRROR ASSY	Cut	455.00 F	*455.00 FL
4	1		*O/S FRONT OUTER WINDOW MOULDING	Not Necessary	119.00 F	*- FL
5	1		*O/S FRONT DOOR HINGE	Not Necessary	75.00 F	*- FL
					Sub Total (\$\$)	3,302.00 1,805.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 180.50
					Total Parts (\$\$)	3,302.00 1,624.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS,PANEL BEAT,REPAIR	New	500.00	450.00
2	TO PUTTY AND SPRAY PAINTING ON AFFECTED AREA	New	800.00	500.00
3	ANTI RUST	New	80.00	60.00
4	WIRING CHECK	New	50.00	30.00
5	TRANSFER DOORS FITTINGS	New	100.00	80.00
Gross Labour Cost (\$)			1,530.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >