

JA AUTOCARE PTE LTD

Blk 24 #03-35
Sin Ming Road
Singapore 570024
Tel : 94513429

Not Notified
11 Days @ 3400k
Penny After Paint
5 days

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581
Attn: Motor Claims Department

ESTIMATE

Date: 13.08.2021
Vehicle no: SMN 1340G 31406 *Tr*
Model: TOYOTA SIENTA
DOA: 11.08.2021

PARTS

- 01) Rear bumper *495.50*
02) Rear bumper clips
03) Rear bumper bracket @\$60.00 x2
04) Rear bumper retainer @\$50.00 x 2
05) Rear Bumper centre pad *235.80*
06) Rear Bumper centre pad reflector rh
07) Rear bumper centre reflector *196.20*
08) Reverse sensor Socket 196.20
09) Rear panel outer
10) Tail gate *1040.40*
11) Tail gate rubber
12) Tail gate centre chrome
13) Tail gate lock
14) Tail gate inner trim board
15) Tail gate inner trim board clips
16) Toyota logo
17) SIENTA emblem
18) Tail lamp assy rh
19) Rear wiper motor assy
Tail remote receiver 489.00 Rd ✓ 127.00
Tailgate panel top garnish 320 D13 ✓ 219.90

\$	Buc 100	650.80	✓
\$	M	80.00	✓
\$	X	120.00	X
\$	In	100.00	X
\$	nd	350.80	✓
\$	nd	120.50	✓
\$	Sm	85.50	X
\$	mg car	350.80	✓
\$	B1	350.00	✓
\$	B1	1,450.80	✓
\$	D13 100	250.80	✓
\$	Sm	320.50	X
\$	nd	330.50	✓
\$	Sm	380.00	X
\$	nn	60.00	X
\$	nn	85.00	✓
\$	nn	95.00	✓
\$	Sm	550.80	X
\$	Sm	980.50	X
\$		6,712.30	
\$		(1,678.07)	Less 25%
\$		5,034.23	

S/Nett

- 20) Rear windscreen sealant and clip
21) Reverse sensor

\$	M	100.00	60k
\$	nd	380.00	200k
\$		480.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

JA AUTOCARE PTE LTD

Blk 24 #03-35

Sin Ming Road

Singapore 570024

Tel : 94513429

ESTIMATE

MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581
Attn: Motor Claims Department

Date: 13.08.2021
Vehicle no: SMN 1340G31406 P
Model: TOYOTA SIENTA
DOA: 11.08.2021


Labour charges

- 22) To dismantle upholstery
- 23) To check wiring
- 24) to apply anti rust chemical
- 25) To dismantle rear windscreen glass
- 26) To knock out dent on affected areas and renew parts
- 27) To putty & respray painting

\$	150.00
\$	120.00
\$	140.00
\$	140.00
\$	1,200.00
\$	1,200.00
\$	2,950.00

606
201
801
1201
8001
6001

Sub Total	\$	8,464.23
-----------	----	----------


for JA AUTOCARE PTE LTD