

ASS. REC. BY:

REF:

MSG/ 21008505/KV f3

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLJ 1849S

Policy No. 29138251ATM

Claims No. 637508

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4-5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMN 3140G

Yr Regn:

07/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Siento

c.c

1496

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

17300

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MHF 22814 35000 64849

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

195/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

11/8/21

D.O.I.

17/8/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/9/21

@ 4.34pm LS \$3400 confirmed with Jenny (Red 5670.97, 62%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 16/9/21-typist

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: Merimen

ump Sum / I.B.I: (\$ LS \$3400

# JA AUTOCARE PTE LTD

Blk 24 #03-35  
Sin Ming Road  
Singapore 570024  
Tel : 94513429

Not Authorized  
1/Rep &  
Pruning After Painting  
4-5 days

## ESTIMATE

MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581  
Attn: Motor Claims Department

Date: 13.08.2021  
Vehicle no: SMN 1348G31406 *Tr*  
Model: TOYOTA SIENTA  
DOA: 11.08.2021

## PARTS

- 01) Rear bumper
- 02) Rear bumper clips
- 03) Rear bumper bracket @\$60.00 x2
- 04) Rear bumper retainer @\$50.00 x 2
- 05) Rear Bumper centre pad
- 06) Rear Bumper centre pad reflector rh
- 07) Rear bumper centre reflector
- 08) Reverse sensor Socket
- 09) Rear panel outer
- 10) Tail gate
- 11) Tail gate rubber
- 12) Tail gate centre chrome
- 13) Tail gate lock
- 14) Tail gate inner trim board
- 15) Tail gate inner trim board clips
- 16) Toyota logo
- 17) SIENTA emblem
- 18) Tail lamp assy rh
- 19) Rear wiper motor assy

\$	<i>Buc 100</i>	650.80	✓
\$	<i>Re</i>	80.00	✓
\$	<i>X</i>	120.00	X
\$	<i>in</i>	100.00	✓
\$	<i>Re</i>	350.80	✓
\$	<i>Re</i>	120.50	✓
\$	<i>in</i>	85.50	X
\$		350.80	✓
\$		350.00	✓
\$	<i>Re</i>	1,450.80	✓
\$	<i>Dis 100</i>	250.80	50
\$	<i>in</i>	320.50	X
\$	<i>Re</i>	330.50	✓
\$	<i>in</i>	380.00	X
\$	<i>Re</i>	60.00	X
\$	<i>Re</i>	85.00	✓
\$	<i>Re</i>	95.00	✓
\$	<i>in</i>	550.80	X
\$	<i>in</i>	980.50	X
\$		6,712.30	
Less 25%	\$	(1,678.07)	
	\$	5,034.23	

## S/Nett

- 20) Rear windscreen sealant and clip
- 21) Reverse sensor

\$	<i>Re</i>	100.00	60
\$	<i>Re</i>	380.00	20
\$		480.00	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# JA AUTOCARE PTE LTD

Blk 24 #03-35

Sin Ming Road

Singapore 570024

Tel : 94513429

## ESTIMATE

MSIG Insurance (Singapore) Pte Ltd  
16 Raffles Quay  
#24-01 Hong Leong Building  
Singapore 048581  
Attn: Motor Claims Department

Date: 13.08.2021  
Vehicle no : SMN 1346G31406  
Model: TOYOTA SIENTA  
DOA : 11.08.2021

## Labour charges

22) To dismantle upholstery	\$	150.00	60h
23) To check wiring	\$	120.00	20h
24) to apply anti rust chemical	\$	140.00	7
25) To dismantle rear windscreen glass	\$	140.00	120h
26) To knock out dent on affected areas and renew parts	\$	1,200.00	?
27) To putty & respray painting	\$	1,200.00	60h
	\$	<u>2,950.00</u>	
Sub Total	\$	8,464.23	

  
for JA AUTOCARE PTE LTD



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission 12/08/2021 15:12 (SGT)  
Date of Accident 11/08/2021 09:00 (SGT)  
Exact Location of Accident Singapore  
Additional Location Information ALONG THIMSON ROAD TOWARDS NOVENA  
Country/State of Loss Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN3140G  
INSURED/POLICYHOLDER  
Is company? No  
Name Of Registered Owner PHANG CHUN YANG  
NRIC No SXXXX128G  
Email Address Pcy5287@gmail.com  
Mobile Phone No (Phone) +65-96158987  
Alternative Phone No +65-96158987

## VEHICLE PARTICULARS

Manufacturer Toyota  
Model Sienta  
Variant -  
Exact purpose for which vehicle was being used at time of accident Private use  
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party  
Vehicle Category Private car  
Transmission Auto  
CC 1496

## INSURANCE COMPANY

Name of Insurance Company Aviva Ltd  
Type of Coverage Comprehensive  
Fleet Policy No  
Policy Number 10996971  
Cover Note Number NA

## DRIVER

Name of Driver KONG HUI SHAN, JANICE  
NRIC No SXXXX038A

Accident report SA0A218C0001



x family

CONTACT POINT

K A K B

AB LMN3140G.

BUS LANE

B: SLJ1849S.

THOMSON ROAD TO NOVEVA.

VERIFIED BY AJAX MARS (ARC)  
REPORTING OFFICER  
HASHIM BIN KAMARI

Policyholder's Signature  
Date & Time:

x family

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.: