

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBC748L210802

Estimate

Customer		Date:	12-08-21
Name:	Sompo Insurance Singapore Private Limited	Vehicle No:	GBC748L
Address:	Motor Claims Department	Model/Make:	Mitsubishi
	50 Raffles Place #05-01 / 06		FB70BB1SRDEA
	Singapore Land Tower Singapore 048623		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Rh Head Lamp <i>CNE</i> 703.58	\$ 768.10	100
2	Side Lamp <i>CNE</i> 184.20	\$ 227.40	
3	Signal Lamp <i>CNE</i> 237.62	\$ 316.60	
	To check all wiring & electrical component for proper function	\$ 30.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 200.00	

Total Parts & Labour of estimate for damaged vehicle

\$ 1,542.10

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Authorized
 13/8/21
 1/5 @ 750
 1 day
 Whiplash after repair
 Submit to insurance.

P-1125-40
 252
 P-844.05
 2-100
 944.05
 20%
 755.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: