



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008508/Uvf3n2	
			Date: 23/08/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 4690A	Veh. Inspected	GBC 748L
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2102397/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	13/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi FB70	c.c	2977
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	FB70BBA20337	Colour	WHITE
	Odometer	26234 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	AUSTONE	6 mm
	L/H Front Tyre	195 R15	AUSTONE	6 mm
	R/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm
	L/H Rear Tyre	195 R15 (D)	AUSTONE	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/08/2021	Inspection Date	13/08/2021
	Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	