

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305482469

Date : 13-08-21

Time of Fax : \_\_\_\_\_

Via Fax : EMAIL

Your Insured : GRD 5944Z

Date of Acc : 12-8-21

Attn: Motor Claims Department

AG

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

B 3819E

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ <u>Jumani Bin Masudin</u>	<b>Tel: 6214 8315 or HP: 9635 5305</b>
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**  
**Fax no. 6546 8156**

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President  
Taxi Accident Repair

6000

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO SHB3819E

DATE: 12. August 2021

MAKE TOYOTA

MVA JUMANI

MODEL PRIUS

DOA: 12. Aug. 2021

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY			\$458.60
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER LOWER COVER			\$220.50
1	REAR BUMPER REINFORCEMENT			\$318.80
1	REAR BUMPER UNDER COVER			\$552.60
1	REAR BUMPER SIDE COVER RH			\$148.40
1	REAR BUMPER TOW COVER			\$82.70
1	ROOFTOP REAR COVER			\$746.26
1	ROOFTOP SIDE COVER LH			\$71.10
1	ROOFTOP SIDE COVER RH			\$71.10
SUB TOTAL				\$1,903.90
LESS 25%				\$380.78
DISCOUNTED TOTAL				\$1,523.12
1	REAR BUMPER MAT			\$50.00
1	REVERSE SENSOR			\$135.70
				\$50.00
Labour Charge				
PANEL BEATING				\$400.00
SPRAY PAINT				\$300.00
REMOVE/REFIX REVERSE SENSOR				\$80.00
TOTAL LABOUR				\$680.00
ESTIMATE TOTAL				\$2,253.12
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NET

NET

INSURER ENQUIRY


Find

insurer

Vehicle reg. no.

GBD5944Z

Date of Accident

12/08/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance ..... **AIG Asia Pacific Insurance Pte....**

Period of Insurance ..... **04/02/2021 - 03/02/2022**

Requested By ..... **Por Moy Juan (COMFORTDELG...**

Requested Date ..... **12/08/2021 16:33**

**Payment details**

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

**General Insurance Association**

Records Management Centre

GST Registration No: **M400017735**

SHB 38192