

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21008517/EQCN2**Date:** 25/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00126772000
Claimant Vehicle No :	YP7486E	Insured Vehicle No :	SMN9919M
Date of Loss:	10/08/2021	Nature of Claim:	TP
		Claim No:	SNM21D204433/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP7486E		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER3SDEB (CBU) (M)	Engine No:	4P10C75497
Reg. Date:	25/10/2017 (Man. Year: 2017)	Chassis No:	FEB21EA21591
Colour:	White	Odometer:	226986 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85R15	Rear Tyre Size:	195/85R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,110.25	1,025.90	5,084.35	83.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,930.00	1,030.00	900.00	46.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,040.25	2,055.90	5,984.35	74.43
Approved Total (Overridden) (\$\$)		1,650.00		
(\$\$)	8,040.25	1,650.00	6,390.25	79.48
+ GST 7.00/7.00% (\$\$)	562.82	115.50	447.32	79.48
Nett Amount (\$\$)	8,603.07	1,765.50	6,837.57	79.48

INSPECTION

Date of Assignment:	17/08/2021		
Date Inspected:	16/08/2021	Inspected At:	Connect3 (HQ) 566 Woodlands Road Singapore 728697
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Oct 2021)	
Parts:	N/A MITSUBISHI CANTER 3.0 D FEB21ER3SDEB (CBU) (M) (Model not available in database)	
Labour:	Repairer's (Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for YP7486E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP LH	Broken	839.65 F	*226.00 FL
2	1		*TAILLAMP HOLDER	Bent	75.00 F	*75.00 FL
3	1		*TAILGATE	Not Necessary	2,998.44 F	*- FL
4	4		*TAILGATE HINGES	Not Necessary	380.00 F	*- FL
5	2		*TAILGATE LOCK HANDLE	Not Necessary	710.16 F	*- FL
6	1		*TAILGATE CORNER BRACKET STOPPER	Not Necessary	22.00 F	*- FL
7	1		*REAR CENTER STEP	Bent	150.00 F	*150.00 FL
8	1		*REAR BUMPER WITH GUARD AND BRACKET	Bent	650.00 F	*600.00 FL
9	1		*REAR NUMBER PLATE	Bent	40.00 FS	*35.00 FS
10	1		*TAILGATE INNER BOARD	Not Necessary	200.00 FS	*- FS
11	1		*60KM-STICKER	Necessary	15.00 FS	*15.00 FS
12	1		*FUSO STICKER	Necessary	15.00 FS	*15.00 FS
13	1		*22 PAX STICKER	Necessary	15.00 FS	*15.00 FS
					Sub Total (\$\$)	
					6,110.25	1,131.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	
					0.00	105.10
					Total Parts (\$\$)	
					6,110.25	1,025.90

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES	New	1,500.00	600.00
2	CHECK WIRING	New	30.00	30.00
3	SPRAY PAINTING	New	400.00	400.00
Gross Labour Cost (\$)			1,930.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >