

CONNECT 3
 566 Woodlands Road (Mandai Estate) Singapore 728697
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Roc: 53360061L
 GST: 53360061L

Steve (CLKK)
16/8/21, 10.00 AM
Mr AL
4 L/S
My AL sy

QT21/YP7486E/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle YP7486E


With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)	
1.	Taillamp LH / BR	1	839.65	226 / 839.65	
2.	Taillamp holder / BT	1	75.00	75.00	✓
3.	Tailgate X nn	1	2,998.44	2,998.44	X
4.	Tailgate hinges X nn	4	95.00	380.00	X
5.	Tailgate lock handle X nn	2	355.08	710.16	X
6.	Tailgate corner bracket stopper X nn	1	22.00	22.00	X
7.	Rear number plate SN / BT	1	40.00	40.00	35 net
8.	Tailgate inner board SN X nn	1	200.00	200.00	X
9.	Rear center step / BT	1	150.00	150.00	✓
10.	Rear bumper with guard and bracket / BT	1	650.00	650.00	600 ✓
11.	Labour charges	1	600 1,500.00	1,500.00	
12.	Check wiring	1	30.00	30.00	✓
13.	Spray painting	1	400.00	400.00	✓
SUB-TOTAL				S\$7,995.25	

- Price exclude 7%gst

60 km - sticker - \$15.00 / AL
 Puso sticker - \$15.00 / AL
 20 pax sticker - \$15.00 / AL

Yours faithfully,



Winnie Chai

HP: 9850-9666



LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part at inspection
- Parts price agreed on inspection
- Third party survey on a non-liable basis
- No legal responsibility accepted
- Surplus value must be returned and
is subject to approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 1051

- 10%

945.90

Nett - 80

L - 1030

2055.90

L/S - 1644.72

= 1650