



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SMF 3744G
Chassis No : JHMGK3850JX227201
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : NGO KENG SIEN
Ins Policy No. :
Date of Accident : 25/5/2021

Document No. : SQT21002503
Date : 12 Aug 2021
Customer No. : WC008
Svc Advisor : NG SIN HAI
Engine No : L13B11031448
Date | Time : 12 Aug 2021 12:00:48 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	OWN DAMAGE CLAIMS-J/NO:						
	POLICY/CLAIMS NO:						
	OWNER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	AUTHORIZED ON:						
	REF NO:						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X NN	1	45.00		45.00	3.15	48.15
33100-T5A-J81	HEADLIGHT ASSY.R. X NN	1	511.50	5	485.92	34.01	519.93
33150-T5A-J81	HEADLIGHT ASSY.L. / CUT	1	511.50	5	485.92	34.01	519.93
60100-T5A-000ZZ	HOOD COMP / DD	1	573.20	5	544.54	38.12	582.66
71105-T5A-000	COVERFR GRILLE X NN	1	12.90	5	12.25	0.86	13.11
71120-TAR-003	GRILLE ASSYFR. X NN	1	275.20	5	261.44	18.30	279.74
91505-TM8-003	CLIP BUMPER / REC DD	4	2.30	5	8.74	0.61	9.35
04711-T5A-000ZZ	FACE FR BUMPER / DD	1	538.10	5	511.19	35.78	546.97
71102-T5A-000	LOWER GRILLE FR BUMPER X NN	1	32.30	5	30.68	2.15	32.83
71103-T5A-000	GARNISHR FR BUMPER X NN	1	12.90	5	12.25	0.86	13.11
71104-T5A-000ZF	COVERFR TOWING X NN	1	15.40	5	14.63	1.02	15.65
71108-T5A-000	GARNISHL FR BUMPER X NN	1	12.90	5	12.25	0.86	13.11
71110-T5A-000	SPOILERFR BUMPER LIP X NN	1	66.20	5	62.89	4.40	67.29
71130-T5A-000ZZ	BEAM COMPFR BUMPER X NN	1	238.70	5	226.76	15.87	242.63
71140-T5A-000	BRACKETR HEADLIGHT X NN	1	25.70	5	24.41	1.71	26.12
71145-T5A-000	BASEFR LICENCE PLATE X NN	1	55.50	5	52.72	3.69	56.41
71190-T5A-000	BRACKETL HEADLIGHT X NN	1	21.90	5	20.80	1.46	22.26
71193-T5A-000	SPACERR FR BUMPER / REC	1	10.40	5	9.88	0.69	10.57
71198-T5A-000	SPACERL FR BUMPER / REC	1	10.40	5	9.88	0.69	10.57
91505-TM8-003	CLIP BUMPER / REC	17	2.30	5	37.14	2.60	39.74

Printed on 12/8/2021 12:11:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)
Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SMF3744G
Chassis No : JHMGK3850JX227201
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : NGO KENG SIEN
Ins Policy No. :
Date of Accident : 25/5/2021

Document No. : SQT21002503
Date : 12. Aug 2021
Customer No. : WC008
Svc Advisor : NG SIN HAI
Engine No : L13B11031448
Date | Time : 12. Aug 2021 12:00:48 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
60211-T5R-A00ZZ	PANEL, R.FR.FENDER X <i>nn</i>	1	425.10	5	403.84	28.27	432.11
60261-T5R-A00ZZ	PANEL, L.FR.FENDER / <i>nn</i>	1	425.10	5	403.84	28.27	432.11
74100-T5A-000	FENDER ASSY, R.FR INNER X <i>nn</i>	1	78.10	5	74.19	5.19	79.38
90682-SEA-003	CLIP ABUMPER <i>3</i> - <i>nn</i>	<i>3</i>	2.60	5	14.82	1.04	<i>743</i> 15.86
91501-TR0-003	CLIP, INNER FENDER - <i>nn</i>	<i>22</i>	2.80	5	58.52	4.10	<i>31-31</i> 62.62
60400-T5B-310ZZ	BULKHEAD COMPFR. X <i>nn</i>	1	407.10	5	386.74	27.07	413.81
80100-T5B-003	CONDENSER ASSY X <i>nn</i>	1	704.40	5	669.18	46.84	716.02
19010-5R1-901	RADIATOR COMP X <i>nn</i>	1	1291.70	5	1227.11	85.90	1313.01
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 X <i>nn</i>	6	23.20	5	132.24	9.26	141.50
Sum Item					<u>6239.77</u>	<u>436.78</u>	<u>6,676.55</u>
BOSUN	SUNDRIES	1	100.00	<i>30</i>	100.00	7.00	107.00
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	<i>150</i>	180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	480.00	X	480.00	33.60	513.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	430.00	X	430.00	30.10	460.10
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN <i>650 x 13</i>	1	4000.00	<i>1950</i>	4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) <i>570 x 3</i>	1	3500.00	<i>1560</i>	3500.00	245.00	3745.00
Sum Labor					<u>8690.00</u>	<u>608.30</u>	<u>9,298.30</u>

Survey By

Date & Time

Excess

Status

Signature

Steve (LKR)

16/8/21, 2:30pm

5 days

P/P

My BIL Sy

Not ALL

EXPLAIN - ?

Total Amount 14,929.77 1,045.08 15,974.85

Total (Inclusive of GST) 15,974.85

Printed on 12/8/2021 12:11:12 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

LKR is a company which verify the Repairer of the following:

- To ensure before the repair work
- To ensure damaged parts are replaced
- Parts which are subject to inspection
- The repair work is done in a proper way
- To ensure the repair work is done in a proper way
- To ensure the repair work is done in a proper way

Approved by Repairer
Signature: