



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SMF3744G

Chassis No : JHMGK3850JX227201

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : NGO KENG SIEN

Ins Policy No. :

Date of Accident : 25/5/2021

Document No. : SQT21002503 Page 1

Date : 12. Aug 2021

Customer No. : WC008

Svc Advisor : NG SIN HAI

Engine No : L13B11031448

Date | Time : 12. Aug 2021 12:00:48 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	OWN DAMAGE CLAIMS-J/NO:						
	POLICY/CLAIMS NO:						
	OWNER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	AUTHORIZED ON :						
	REF NO :						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33100-T5A-J81	HEADLIGHT ASSY.R. X	1	511.50	5	485.92	34.01	519.93
33150-T5A-J81	HEADLIGHT ASSY.L. / CUT	1	511.50	5	485.92	34.01	519.93
60100-T5A-000ZZ	HOOD COMP / DD	1	573.20	5	544.54	38.12	582.66
71105-T5A-000	COVERFR.GRILLE X	1	12.90	5	12.25	0.86	13.11
71120-TAR-003	GRILLE ASSYFR. X	1	275.20	5	261.44	18.30	279.74
91505-TM8-003	CLIP,BUMPER / nec DD	4	2.30	5	8.74	0.61	9.35
04711-T5A-000ZZ	FACE,FR.BUMPER / DD	1	538.10	5	511.19	35.78	546.97
71102-T5A-000	LOWER GRILLE,FR.BUMPER X	1	32.30	5	30.68	2.15	32.83
71103-T5A-000	GARNISHR.FR.BUMPER X	1	12.90	5	12.25	0.86	13.11
71104-T5A-000ZF	COVERFR.TOWING X	1	15.40	5	14.63	1.02	15.65
71108-T5A-000	GARNISHL.FR.BUMPER X	1	12.90	5	12.25	0.86	13.11
71110-T5A-000	SPOILERFR.BUMPER LIP X	1	66.20	5	62.89	4.40	67.29
71130-T5A-000ZZ	BEAM COMPFR.BUMPER X	1	238.70	5	226.76	15.87	242.63
71140-T5A-000	BRACKETR.HEADLIGHT X	1	25.70	5	24.41	1.71	26.12
71145-T5A-000	BASEFR.LICENCE PLATE X	1	55.50	5	52.72	3.69	56.41
71190-T5A-000	BRACKETL.HEADLIGHT X	1	21.90	5	20.80	1.46	22.26
71193-T5A-000	SPACERR.FR.BUMPER / nec	1	10.40	5	9.88	0.69	10.57
71198-T5A-000	SPACERL.FR.BUMPER / nec	1	10.40	5	9.88	0.69	10.57
91505-TM8-003	CLIP,BUMPER / nec	17	2.30	5	37.14	2.60	39.74

Printed on 12/8/2021 12:11:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SMF3744G
Chassis No : JHMGK3850JX227201
Model : JAZZ 1.3LXR CVT 18YM (EURO 6)
Owner's Name : NGO KENG SIEN
Ins Policy No. :
Date of Accident : 25/5/2021

Document No. : SQT21002503 Page 2
Date : 12. Aug 2021
Customer No. : WC008
Svc Advisor : NG SIN HAI
Engine No : L13B11031448
Date | Time : 12. Aug 2021 12:00:48 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
60211-T5R-A00ZZ	PANEL ,R.FR.FENDER X	1	425.10	5	403.84	28.27	432.11
60261-T5R-A00ZZ	PANEL,L.FR.FENDER /	1	425.10	5	403.84	28.27	432.11
74100-T5A-000	FENDER ASSY,R.FR INNER X	1	78.10	5	74.19	5.19	79.38
90682-SEA-003	CLIP ABUMPER X - APC	6	2.60	5	14.82	1.04	15.86
91501-TR0-003	CLIP,INNER FENDER / - APC	22	2.80	5	58.52	4.10	62.62
60400-T5B-310ZZ	BULKHEAD COMPFR. X	1	407.10	5	386.74	27.07	413.81
80100-T5B-003	CONDENSER ASSY X	1	704.40	5	669.18	46.84	716.02
19010-5R1-901	RADIATOR COMP X	1	1291.70	5	1227.11	85.90	1313.01
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 X	6	23.20	5	132.24	9.26	141.50
Sum Item					6239.77	436.78	6,676.55
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	150	180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	480.00	X	480.00	33.60	513.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	430.00	X	430.00	30.10	460.10
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN 650 x 13	1	4000.00	1950	4000.00	280.00	4280.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) 570 x 3	1	3500.00	1560	3500.00	245.00	3745.00
Sum Labor					8690.00	608.30	9,298.30

Survey By : Steve (LKR)
Date & Time : 16/8/21, 2.30pm
Excess : 5 days
Status : PIP
Signature : My Bil sy
NH1 ALL
EXcess - ?

Total Amount 14,929.77 1,045.08 15,974.85
Total (Inclusive of GST) 15,974.85

Printed on 12/8/2021 12:11:12 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: