

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0273/21
DATE : 10-AUG-2021

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MS TAY GEK KIAN ROSALIND MRS ROSALIND PERERA
ADDRESS : 68 UPPER SERANGOON VIEW
#04-23
S(533884)
TELEPHONE NO : 88097331

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 1800076463-03
VEHICLE NO : SMC2529J
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2640763A
CHASSIS NO : SJNFEAJ11U2311936
MILEAGE : 27675 KM
DATE IN : 10/08/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 09/08/2021

not authorized
LKK
17/8/21
take photo before repair.
3 days.

p/p 2130-36

-9645 0084 elmu@tanchang.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SMC2529J

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RR END PANEL RENEW REAR BUMPER 390	1170.00	585 ,
2 ZZ/002	CHARGES TO SPRAY PAINTING REAR END PANEL AND REAR BUMPER	750.00	500 ,
3 ZZ/003	RENEW REVERSE SENSOR	110.00	✓ ,
4 ZZ/004	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK WIRING SYSTEM	48.00	✓ ,
5 ZZ/005	COMPUTER CHECK DIAGNOSIS 11	120.00	X
TOTAL LABOUR CHARGES		2198.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SMC2529J

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 REVERSE SENSOR(4EYE)	SENSOR-4-FUM		short	250.00 ✓
2 RH SIDE BRACKET RR BUMPER	85220-4EAOA	17 38.90	X	
3 LH SIDE BRACKET RR BUMPER	85221-4EAOA	17 38.90	X	
4 RH STAY RR BUMPER	H5210-4EAMA	17 141.00	X	
5 LH STAY RR BUMPER	H5211-4EAMA	17 141.00	X	
6 REINFORCEMENT RR BUMPER	H5030-4EAMA	12 691.50	X	
7 ENERGY ABSORBER RR BUMPER	85090-HV00A	17 141.40	X	
8 TOW HOOK COVER RR BUMPER	85071-HV00A	17 18.80	X	
9 REAR BUMPER	85022-HV00H	De 796.70		
10 SUNDRIES	NPN		17	100.00 X
SUB TOTAL		2008.20	0.00	350.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		401.64	0.00	0.00
GRAND TOTAL		1606.56	0.00	350.00
OVERALL TOTAL		1956.56		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

P 796.70
 20%
 P. 637.36
 S.N 250
 L-1243
 2130.36

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SMC2529J

TOTAL LABOUR CHARGES	2198.00
TOTAL SPARE PARTS CHARGES	1956.56

GRAND TOTAL	4154.56 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.