

ASS. REC. BY:

REF:

LPC / 21008528 / KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

822k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21 days

Res.: Yes or No

Lump Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

07/26

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

16/8

No parts in local market

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

The Motor Claims Department
M/s Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

File No :
Date :

SH/2021/143/08/005/od
13-August-2021

Not withstanding
May be 7600
Ex 8500

Estimated cost of repair for vehicle no : **GBC338L** Toyota Town Ace
Policy no: Z21VC05007458 Accident Date: 6/8/2021

Description	Quantity	Cost Price
Bonnet	1	\$ <i>R1</i> 350.00 ✓
RH Bonnet hinge	1	\$ <i>Di</i> 55.00 ✓
LH Bonnet hinge	1	\$ <i>R1</i> 55.00 ✓
Bonnet lock	1	\$ <i>Tr</i> 80.00 ✓
Bonnet emblem	1	\$ <i>Ac</i> 80.00 ✓
RH head lamp	1	\$ <i>CM</i> 720.00 ✓
LH head lamp	1	\$ <i>Bu</i> 720.00 ✓
Front bumper	1	\$ <i>CM</i> 680.00 ✓
Front bumper clips (1 set)	1	\$ <i>Tr</i> 28.00 ✓
LH Front bumper retainer	1	\$ <i>CM</i> 55.00 ✓
Front bumper tow cover	1	\$ <i>Di</i> 45.00 ✓
LH front fender	1	\$ <i>R1</i> 350.00 ✓
LH front fender wheel cowling	1	\$ <i>CM</i> 190.00 ✓
LH front fender wheel cowling clips (1 set)	1	\$ <i>Tr</i> 18.00 ✓
LH front door	1	\$ <i>Bu</i> 2,200.00 ✓
LH front door hinge top	1	\$ 70.00 ?
LH front door hinge lower	1	\$ 70.00 ?
LH front door check	1	\$ <i>Tr</i> 95.00 X
LH front door inner trim board	1	\$ 420.00 ?
LH front door window regulator	1	\$ <i>R</i> 280.00 X
Front support panel	1	\$ <i>R1</i> 1,200.00 ✓
Bonnet lock centre bracket	1	\$ 90.00 ?
Air con condensor	1	\$ <i>Tr/Tr</i> 880.00 ✓
Air con condensor pipe inlet	1	\$ 380.00 ?
Air con condensor pipe outlet	1	\$ 360.00 ?
Air con condensor fan motor	1	\$ 450.00 ?
Air con condensor fan blade	1	\$ 180.00 ?
Air con condensor fan cowling	1	\$ 250.00 ?
Radiator	1	\$ 780.00 ?
Radiator top hose	1	\$ 70.00 ?
Radiator fan motor	1	\$ 450.00 ?
Radiator fan blade	1	\$ 180.00 ?
Radiator fan cowling	1	\$ 250.00 ?
LH front wheel house panel	1	\$ <i>R1</i> 680.00 ✓
LH front wheel house-chassis member closing panel	1	\$ 380.00 ?
LH front door hinge pillar	1	\$ <i>R1</i> 450.00 ✓

LH front door frame complete pillar?	1	\$	380.00	?
Firewall panel	1	\$	1,800.00	?
Wiper panel	1	\$	580.00	✓
Wiper panel garnish	1	\$	280.00	✓
LH front wiper arm	1	\$	110.00	✓
Front wiper linkage	1	\$	280.00	✓
Front wiper motor	1	\$	480.00	?
Front windscreen	1	\$	480.00	✓
Front windscreen moulding	1	\$	65.00	✓
Dashboard	1	\$	980.00	✓
LH dashboard air bag	1	\$	3,800.00	✓
LH dashbaord air con vent	1	\$	120.00	?
LH windscreen pillar inner trim	1	\$	380.00	✓
Air con blower box	1	\$	1,950.00	?
RH front seat belt	1	\$	480.00	X

\$ 25,756.00
Add 15% \$ 3,863.40
\$ 29,619.40

LH front door company sticker	1	S. nett	\$	25.00	✓
Front windscreen sealant	1	S. nett	\$	80.00	✓
Front windscreen inner rubber seal	1	S. nett	\$	28.00	✓
Engine coolant	1	S. nett	\$	30.00	?
IU bracket	1	S. nett	\$	25.00	✓

To remove and reinstall front windscreen and conduct water leak test \$ 120.00 ✓

To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality \$ 120.00 100%

To remove and install dashboard and centre console, including instrument panel, centre info screen, radio, climate control module \$ 280.00 250%

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair firewall, bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment \$ 1,400.00 1300%

To spray paint affected front and inner damaged portion inclusive of preparatory works and material \$ 1,300.00 1200%

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp

\$ 40.00 20/

Towing charges

\$ 60.00 ✓

\$ 33,127.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/08/2021 17:34 (SGT)
Date of Accident 06/08/2021 15:30 (SGT)
Exact Location of Accident New Upper Changi Rd, Singapore
Additional Location Information slip road of New Upper Changi Road towards Tanah Merah Kechil Road
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBC338L

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Monli Curtain
Company Reg No 5XXXX100L
Email Address alvin1998@hotmail.sg
Mobile Phone No (Phone) +65-94368766
Alternative Phone No (Home) +65-94368766

VEHICLE PARTICULARS

Manufacturer Toyota
Model Town Ace 1.5 DX M
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Manual
CC 1495

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number Z21VC05007458
Cover Note Number -

DRIVER

Name of Driver Tan Hong Thye

> Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Business

Vehicle Details

100L

Vehicle No.:

GBC338L

Vehicle to be Exported:

Yes

Intended Deregistration Date:

10 Aug 2021

Vehicle Make:

TOYOTA

Vehicle Model:

TOWN ACE 1.5 DX M

Primary Colour:

White

Manufacturing Year:

2009

Engine No.:

3SZDBK6300

Chassis No.:

S402M0016229

Maximum Power Output:

-

Open Market Value:

\$23,824.00

Original Registration Date:

24 Feb 2011

First Registration Date:

24 Feb 2011

Transfer Count:

1

Actual ARF Paid:

\$1,192.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

23 Feb 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$17,236.00

COE Rebate Amount:

\$16,315.00

Total Rebate Amount:

\$16,315.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 10 Aug 2021

OK