

The Motor Claims Department
M/s Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

File No :
Date :

SH/2021/143/08/005/od
13-August-2021

Not withanik
May be 7600
Ex 8500/

Estimated cost of repair for vehicle no : **GBC338L** Toyota Town Ace
Policy no: **Z21VC05007458** Accident Date: **6/8/2021**

Description	Quantity	Cost Price
Bonnet	1	\$ <i>R1</i> 350.00 ✓
RH Bonnet hinge	1	\$ <i>Di</i> 55.00 ✓
LH Bonnet hinge	1	\$ <i>R1</i> 55.00 ✓
Bonnet lock	1	\$ <i>Tr</i> 80.00 ✓
Bonnet emblem	1	\$ <i>Ac</i> 80.00 ✓
RH head lamp	1	\$ <i>CM</i> 720.00 ✓
LH head lamp	1	\$ <i>Bu</i> 720.00 ✓
Front bumper	1	\$ <i>CM</i> 680.00 ✓
Front bumper clips (1 set)	1	\$ <i>Tr</i> 28.00 ✓
LH Front bumper retainer	1	\$ <i>CM</i> 55.00 ✓
Front bumper tow cover	1	\$ <i>Di</i> 45.00 ✓
LH front fender	1	\$ <i>R1</i> 350.00 ✓
LH front fender wheel cowling	1	\$ <i>CM</i> 190.00 ✓
LH front fender wheel cowling clips (1 set)	1	\$ <i>Tr</i> 18.00 ✓
LH front door	1	\$ <i>Bu</i> 2,200.00 ✓
LH front door hinge top	1	\$ 70.00 ?
LH front door hinge lower	1	\$ 70.00 ?
LH front door check	1	\$ <i>Tr</i> 95.00 X
LH front door inner trim board	1	\$ 420.00 ?
LH front door window regulator	1	\$ <i>R</i> 280.00 X
Front support panel	1	\$ <i>R1</i> 1,200.00 ✓
Bonnet lock centre bracket	1	\$ 90.00 ?
Air con condensor	1	\$ <i>Tr/R1</i> 880.00 ✓
Air con condensor pipe inlet	1	\$ 380.00 ?
Air con condensor pipe outlet	1	\$ 360.00 ?
Air con condensor fan motor	1	\$ 450.00 ?
Air con condensor fan blade	1	\$ 180.00 ?
Air con condensor fan cowling	1	\$ 250.00 ?
Radiator	1	\$ 780.00 ?
Radiator top hose	1	\$ 70.00 ?
Radiator fan motor	1	\$ 450.00 ?
Radiator fan blade	1	\$ 180.00 ?
Radiator fan cowling	1	\$ 250.00 ?
LH front wheel house panel	1	\$ <i>R1</i> 680.00 ✓
LH front wheel house-chassis member closing panel	1	\$ 380.00 ?
LH front door hinge pillar	1	\$ <i>R1</i> 450.00 ✓

LH front door frame complete pillar?	1	\$	380.00	✓
Firewall panel	1	\$	1,800.00	✓
Wiper panel	1	\$	580.00	✓
Wiper panel garnish	1	\$	280.00	✓
LH front wiper arm	1	\$	110.00	✓
Front wiper linkage	1	\$	280.00	✓
Front wiper motor	1	\$	480.00	✓
Front windscreen	1	\$	480.00	✓
Front windscreen moulding	1	\$	65.00	✓
Dashboard	1	\$	980.00	✓
LH dashboard air bag	1	\$	3,800.00	✓
LH dashbaord air con vent	1	\$	120.00	✓
LH windscreen pillar inner trim	1	\$	380.00	✓
Air con blower box	1	\$	1,950.00	✓
RH front seat belt	1	\$	480.00	X
		\$	25,756.00	
	Add 15%	\$	3,863.40	
		\$	29,619.40	

LH front door company sticker	1	S. nett	\$	25.00	✓
Front windscreen sealant	1	S. nett	\$	80.00	✓
Front windscreen inner rubber seal	1	S. nett	\$	28.00	✓
Engine coolant	1	S. nett	\$	30.00	✓
IU bracket	1	S. nett	\$	25.00	✓

To remove and reinstall front windscreen and conduct water leak test \$ 120.00 ✓

To remove and check air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality \$ 120.00 100%

To remove and install dashboard and centre console, including instrument panel, centre info screen, radio, climate control module \$ 280.00 250%

To remove front damaged parts, to jack out front support panel, front body, and cut out damaged parts, to straighten out front chassis, to reweld, reshape and repair firewall, bonnet hinge panel, front fender and inner panel, head lamp inner panel, front support panel, front chassis member, to replace damaged parts and adjust body panel alignment \$ 1,400.00 1300%

To spray paint affected front and inner damaged portion inclusive of preparatory works and material \$ 1,300.00 1200%

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp

\$ 40.00 20/

Towing charges

\$ 60.00 ✓

\$ 33,127.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: