



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM21008531/Kgs3q2 Date: 15/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMR 491S	Veh. Inspected	PC 7320A
	Policy No.	P1305555	Coverage (\$)	0.00
	Claim No.	S1M03EZM	Excess (\$)	0.00
	Assign From		Assign Date	13/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE GL (A)	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GDH2232000331	Colour	WHITE
	Odometer	163812 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	GREEN MAX	6 mm
	L/H Front Tyre	195 R15X8	GREEN MAX	6 mm
	R/H Rear Tyre	195 R15X8	GREEN MAX	6 mm
	L/H Rear Tyre	195 R15X8	GREEN MAX	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/08/2021	Inspection Date	17/08/2021
	Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	