



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108608

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/12/2021
Reference CC6/CTI21008533/R1ea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKF 2225T
Insured Veh. PC 6061D
Claim No. SNM21D204498/C02
Policy No. DMB1SNW00010262000
Accident Date 13/08/2021
Inspection Date 16/08/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21008533/R1ea3q2 Date: 15/12/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 6061D	Veh. Inspected	SKF 2225T	
Policy No.	DMB1SNW00010262000	Coverage (\$)	0.00	
Claim No.	SNM21D204498/C02	Excess (\$)	0.00	
Assign From		Assign Date	16/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5X A	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11115708	Colour	GREY	
Odometer	141655 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	13/08/2021	Inspection Date	16/08/2021	
Survey held at	48 TOH GUAN ROAD EAST #02-146/147			
Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 2225T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	880.00	880.00
10	REAR BUMPER CLIP @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	35.00	-
1	REAR BUMPER RETAINER LH	NOT NECESSARY	35.00	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	150.00	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	150.00	-
1	TAILGATE	BENT	1,080.00	1,080.00
1	TAILGATE LOCK	NOT NECESSARY	280.00	-
1	TAILGATE RUBBER SEAL	NECESSARY	120.00	120.00
1	REAR VEZEL EMBLEM	NECESSARY	80.00	80.00
1	REAR HONDA EMBLEM	NOT NECESSARY	80.00	-
1	REAR SPARE TIRE BOARD COVER	NOT NECESSARY	350.00	-
1	REAR TOOLS SPONGE BOX /TRAY	NOT NECESSARY	250.00	-
1	END PANEL TOP GARNISH	NOT NECESSARY	200.00	-
1	END PANEL	TO REPAIR SEE LABOUR	480.00	-
2	REAR BUZZER @\$110.00	NOT NECESSARY	220.00	-
	LESS 20% DISCOUNT		-	-442.00
			4,440.00	1,768.00
	<u>SPECIAL NETT ITEMS</u>			
2	REVERSE SENSOR @\$200.00 (SN)	SERVICEABLE	400.00	-
1	LICENSE PLATE & CASING (SN)	SCRATCHED	40.00	35.00
			440.00	35.00
	<u>LABOUR</u>			
	SPRAY PAINTING REAR BUMPER ,TAILGATE & END PANEL.		900.00	400.00
	REPLACE REAR INCLUDING FITTING ,CUT ,WELD AND RE-ALIGN.INCLUSIVE OF THE REPAIR OF END PANEL .		900.00	500.00
	REMOVE AND REFIT REAR BUMPER REVERSE SENSOR .		80.00	60.00
	REPAIR ,REPLACE AND REFIT AFFECTED ACCIDENT AREA.	NOT NECESSARY	80.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER TAILGATE FITTING & WINDOW MECHANISM TO NEW TAILGATE .		80.00	60.00
	APPLY RUST PROOFING ON REPLACED /REPAIRED PANEL.		100.00	40.00
	CHECK AND RECTIFY ELECTRICAL WIRING .	NOT NECESSARY	30.00	-
			2,170.00	1,060.00
GRAND TOTAL			7,050.00	2,863.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00
---	--	--	--	-----------------

Report Ref No. CC6/CTI21008533/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 2225T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKF 2225T

RE-INSPECTION

