

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-163 TG

DATE : 13-Aug-2021

POLICY NO. : FWD PNPV2017-00003264-04

VEHICLE REG. NO. : SKF2225T

VEHICLE MAKE : HONDA VEZEL 1.5X A

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper <i>pc</i>	1	\$ 880.00	\$ 880.00
2	Rear Bumper Clip <i>na</i>	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH <i>X nn</i>	1	\$ 35.00	\$ 35.00 <i>X</i>
4	Rear Bumper Retainer LH <i>X nn</i>	1	\$ 35.00	\$ 35.00 <i>X</i>
5	Rear Bumper Reflector RH <i>X nn</i> <i>2210</i>	1	\$ 150.00	\$ 150.00 <i>X</i>
6	Rear Bumper Reflector LH <i>X nn</i> <i>202</i>	1	\$ 150.00	\$ 150.00 <i>X</i>
7	Tailgate <i>bt</i> <i>1768</i>	1	\$ 1,080.00	\$ 1,080.00
8	Tailgate Lock <i>+ nn</i>	1	\$ 280.00	\$ 280.00 <i>X</i>
9	Tailgate Rubber Seal <i>na</i>	1	\$ 120.00	\$ 120.00
10	Rear Vezel Emblem <i>na</i>	1	\$ 80.00	\$ 80.00
11	Rear Honda Emblem <i>X nn</i>	1	\$ 80.00	\$ 80.00 <i>X</i>
12	Rear Spare Tire Board Cover <i>X nn</i>	1	\$ 350.00	\$ 350.00 <i>X</i>
13	Rear Tools Sponge Box/Tray <i>X nn</i>	1	\$ 250.00	\$ 250.00 <i>X</i>
14	End Panel Top Garnish <i>X nn</i>	1	\$ 200.00	\$ 200.00 <i>X</i>
15	End Panel <i>Repair</i>	1	\$ 480.00	\$ 480.00 <i>X R</i>
16	Rear Buzzer <i>X nn</i>	2	\$ 110.00	\$ 220.00 <i>X</i>
Total Spare Parts				\$ 4,440.00
SPECIAL NETT				
17	<i>Licence Plate - casing</i> <i>35</i>	1	\$ 40	\$ 40. <i>35</i>
18	Reverse Sensor <i>X nn</i> <i>35</i>	2	\$ 200.00	\$ 400.00 <i>200? X</i>
Total Special Nett				\$ 400.00
LABOUR				
19	Spray Painting Rear Bumper, Tailgate & End Panel	1	\$ 900.00	\$ 900.00 <i>500 400</i>
20	Replace Rear including Fitting, Cut, Weld and Re-align <i>1060</i>	1	\$ 900.00	\$ 900.00 <i>500</i>
21	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00 <i>60</i>
22	Repair, Replace and Refit Affected Accident Area	1	\$ 80.00	\$ 80.00 <i>X nn</i>
23	Transfer Tailgate Fitting & Window Mechanism to New Tailgate	1	\$ 80.00	\$ 80.00 <i>60</i>
24	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00 <i>40</i>
25	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00 <i>X nn</i>
Total Labour				\$ 2,170.00
Amount Before Excess				\$ 7,010.00

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.

SA002180
ENTRY DATE:
SUBMITTED BY:
VERSION: 1

ARC

Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2108-163 TG
DATE : 13-Aug-2021
POLICY NO. : FWD PNPV2017-00003264-04
VEHICLE REG. NO. : SKF2225T
VEHICLE MAKE : HONDA VEZEL 1.5X A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

*Rasul - Hp 900 10068
5 days / Lump sum
16/08/12 @ 1010 / Resurvey after repair*

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.			
			Add GST @ 7%	490.70
			Total Amount Payable	\$ 7,500.70

1768
35
1060

2863
20%
2290.40
L/s - 2,300
=====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: