

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-163 TG

DATE : 13-Aug-2021

POLICY NO. : FWD PNPV2017-00003264-04

VEHICLE REG. NO. : SKF2225T

VEHICLE MAKE : HONDA VEZEL 1.5X A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Bumper	1	\$ 880.00	\$ 880.00
2	Rear Bumper Clip	10	\$ 5.00	\$ 50.00
3	Rear Bumper Retainer RH	1	\$ 35.00	\$ 35.00
4	Rear Bumper Retainer LH	1	\$ 35.00	\$ 35.00
5	Rear Bumper Reflector RH	1	\$ 150.00	\$ 150.00
6	Rear Bumper Reflector LH	1	\$ 150.00	\$ 150.00
7	Tailgate	1	\$ 1,080.00	\$ 1,080.00
8	Tailgate Lock	1	\$ 280.00	\$ 280.00
9	Tailgate Rubber Seal	1	\$ 120.00	\$ 120.00
10	Rear Vezel Emblem	1	\$ 80.00	\$ 80.00
11	Rear Honda Emblem	1	\$ 80.00	\$ 80.00
12	Rear Spare Tire Board Cover	1	\$ 350.00	\$ 350.00
13	Rear Tools Sponge Box/Tray	1	\$ 250.00	\$ 250.00
14	End Panel Top Garnish	1	\$ 200.00	\$ 200.00
15	End Panel	1	\$ 480.00	\$ 480.00
16	Rear Buzzer	2	\$ 110.00	\$ 220.00
Total Spare Parts				\$ 4,440.00
<u>SPECIAL NETT</u>				
17		1		\$ -
18	Reverse Sensor	2	\$ 200.00	\$ 400.00
Total Special Nett				\$ 400.00
<u>LABOUR</u>				
19	Spray Painting Rear Bumper, Tailgate & End Panel	1	\$ 900.00	\$ 900.00
20	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 900.00	\$ 900.00
21	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 80.00
22	Repair, Replace and Refit Affected Accident Area	1	\$ 80.00	\$ 80.00
23	Transfer Tailgate Fitting & Window Mechanism to New Tailgate	1	\$ 80.00	\$ 80.00
24	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
25	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,170.00
Amount Before Excess				\$ 7,010.00

Estimate prepared by: Ken Ho

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started.

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2108-163 TG
DATE : 13-Aug-2021
POLICY NO. : FWD PNPV2017-00003264-04
VEHICLE REG. NO. : SKF2225T
VEHICLE MAKE : HONDA VEZEL 1.5X A

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.				
Add GST @ 7%				490.70
Total Amount Payable				\$ 7,500.70