

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 28 Sep 2021

## **Preliminary Advice**

Insured : SLN9758Y  
Vehicle No  
TP Vehicle : SMJ1687E Accident Date : 10/08/2021  
No  
Make : MAZDA CX-3 Assignment Date : 16/08/2021  
Date of : 20/09/2021 Est. Duration of : 4  
Inspection Repair  
Inspection At : TRANS EUROKARS PTE LTD (UBI)  
5 UBI CLOSE  
SINGAPORE 408605

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,280.92
Revised Amount	:S\$	3,885.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,885.60

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair

:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.