

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0650/2021/ZK
DATE : 11-Aug-21
WIP : 39011

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/8/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : KHOO JUNWEI (QIU JUNWEI)
ADDRESS : 21 JALAN RAJA UDANG
#29-04
SINGAPORE 329215
TELEPHONE : HP +65 96883721
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210058622
VEHICLE NO : **SNB 948 P**
MODEL CODE : AUDI A6 2.0 TFSI S
MODEL YEAR : 10/6/2021
ENGINE NO : DKY 015289
CHASSIS NO : WAUZZZF25MN053762
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Aug-21
PLACE OF ACCIDENT : NEAR LOR 23 GEYLANG BUS STATION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNB 948 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRI., TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY FOR LHS FRONT DOOR.	S/N \$ 280.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER , LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	1000
5	TO RESPRAY FRONT BUMPER,BONNET,LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 4,000.00	1650
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	192
TOTAL LABOUR CHARGES		\$ 7,944.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 948 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Behind</i>	1	\$ 2,832.00	✓	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 650.00	+	
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new</i>	1	\$ 222.00	+	
4	FRONT BUMPER ADAPTER - LH ?	1	\$ 39.00	?	
5	FRONT BUMPER REINFORCEMENT COVER - LH ?	1	\$ 111.00	?	
6	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1	\$ 210.00	?	
7	FRONT AIR GUIDE GRILLE - LH <i>cut</i>	1	\$ 434.00	✓	
8	FRONT BUMPER AIR GUIDE - LH <i>new</i>	2	\$ 50.00	+	
9	FRONT BUMPER REINFORCEMENT FOAM <i>new</i>	1	\$ 226.00	+	
10	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 1,012.00	+	
11	POP RIVET <i>new</i>	6	\$ 5.00	+	
12	FRONT BUMPER SUPPORT ?	2	\$ 59.00	?	
13	FRONT BUMPER BRACKET - LH ?	1	\$ 54.00	?	
14	FRONT BUMPER GUIDE SECTION - LH ?	1	\$ 44.00	?	
15	FRONT BUMPER TOP COVER <i>new</i>	1	\$ 126.00	+	
16	FRONT PARKING AID SENSOR <i>new</i>	1	TBC	+	
17	FRONT PARKING AID SENSOR SEAL <i>new</i>	4	\$ 14.00	+	
18	HORN - LOW TONE ?	1	\$ 216.00	+	
19	HORN BRACKET <i>new</i>	1	\$ 47.00	+	
20	FRONT FENDER - LH <i>Behind</i>	1	\$ 1,468.00	✓	
SUB TOTAL SPARE PARTS		:	\$ 7,819.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNB 948 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER ATTACHMENT PARTS <i>Not in</i>	1	\$ 42.00	X
22	FRONT FENDER BRACE - LH ?	1	\$ 118.00	?
23	FRONT FENDER BRACKET - LH UPPER ?	1	\$ 44.00	?
24	FRONT HEADLIGHT MOUNTING - LH ?	1	\$ 118.00	?
25	FRONT HEADLIGHT - LH <i>Cracked</i>	1	\$ 8,624.00	✓
26	FRONT HEADLIGHT LIFT CYLINDER - LH ?	1	\$ 198.00	?
27	FRONT HEADLIGHT BRACKET - LH ?	1	\$ 6.00	?
28	FRONT HEADLIGHT LIFT CYLINDER HOSE <i>Not in</i>	1	\$ 182.00	X
29	FRONT FENDER TOP COVER - LH ?	1	\$ 36.00	?
30	FRONT WHEEL HOUSING LINER - LH <i>Not in</i>	1	\$ 275.00	X
31	FRONT WHEEL HOUSING LINER ATTACHEMENT PART <i>Not in</i>	1	\$ 71.00	X
32	FRONT WHEEL SPOILER - LH <i>Not in</i>	1	\$ 166.00	X
33	FRONT WHEEL STONE GUARD - LH <i>Not in</i>	1	\$ 51.00	X
34	FRONT WINDOW CHORME TRIM STRIP - LH OUTER <i>Not in</i>	1	\$ 200.00	X
35	FRONT WINDOW CHORME TRIM STRIP GUIDE - LH <i>Not in</i>	1	\$ 257.00	X
36	SUNDRIES ?		\$ 350.00	?
TOTAL SPARE PARTS		:	\$ 18,557.00	
TOTAL LABOUR CHARGES		:	\$ 7,944.00	
GRAND TOTAL		:	\$ 26,501.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan L.
SURVEYED DATE :
AUTHORISED DATE : 13/08/21.
EXCESS COST :
LIABILITY :
REMARKS : Not Authorized, 05 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT