

MSIA

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Vehicle No: SLB9233H  
 Model and make: Kia Cerato K3

EstimateQty Spare partsList price

1	Rear bumper	\$	✓ 688.00	BR ✓
1	Rear bumper RH side retainer	\$	✓ 32.00	NECV
1	Rear bumper lower spoiler	\$	<del>347.00</del>	NDX
1	Rear windscreen glass rubber seal	\$	✓ 37.00	NECV
1	RH rear fender	\$	✓ 1,100.00	DDV
1	RH rear fender splash shield	\$	<del>413.00</del>	NDX
1	RH taillamp assy	\$	418.20 <del>772.00</del>	CUTV
1	RH rear door	\$	✓ 1,225.00	DDV
1	RH rear door frame black tape (no.1)	\$	✓ 14.77	} NECV
1	RH rear door frame black tape (no.2)	\$	✓ 14.77	
1	RH rear door outer moulding	\$	<del>109.51</del>	NDX
1	RH rear door glass	\$	<del>374.70</del>	NDX
1	RH rear shock absorber	\$	<del>385.00</del>	} ? NDX
1	RH rear wheel bearing	\$	<del>330.00</del>	
1	Rear axle beam	\$	2,200.00	NDX

\$ 7,742.75  
 -10% \$ 774.28  
 \$ 6,968.48  
 @ 10%  
 3,529.74  
 352.97  
 3,176.77

Qty Spare partsSpecial Nett price

1set	Rear bumper clips	\$	30.00	70.00	NECV
1	RH rear sport rim	\$	380.00	<del>800.00</del>	CUTV
1	RH rear tyre	\$	200.00	320.00	CUTV
1	Brake fluid	\$		50.00	NNX
1	Rear windscreen glass sealant	\$	30.00	70.00	NECV
1	Rear windscreen glass inner seal	\$		50.00	NNX
			640.00		

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.  
 To panel beating, cut / weld and re-align all affected panels

\$ 800.00 1,000.00 ✓

Spray painting on affected panels

\$ 700.00 900.00 ✓

Check all wiring and all lighting system

\$ 80.00 NNX

Apply rust coating chemical on affected panels	S	<del>80.00</del> NNX
Remove and reinstall rear windscreen glass to assist repair	S	120.00 200.00 ✓
Remove and reinstall rear inner trims, boards, garnish, seats and roof lining to assist repair	S	<del>350.00</del> NNX
Remove and reinstall rear bumper reverse sensors to assist repair	S	60.00 70.00 ✓
Remove and reinstall RH rear door inner components to new door	S	80.00 100.00 ✓
Conduct and adjust wheel alignment system	S	60.00 100.00 ✓
Remove and replace rear undercarriage parts to assist repair	S	450.00 ? NNX
		<u>1820.00</u>

Total: S 11,658.48

Survey & Resurvey

16/8/2021

1536 hrs

TOTUM

WV

Parts 3694.27

SN 670.00

Labour 2320.00

6684.27

@20% 1336.85

5347.42

Lump sum repair

Repair days 6

LS 5,350/2

TOTUM lin

11/9/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Qty	Supplementary	Vehicle No: Model and make:	SLB9233H Kia K3
1	RH rocker panel	\$	✓ 575.00 DDV
		\$	575.00 DDV
		-10% \$	57.50
		\$	✓ 517.50
1	RH rocker panel joint sealant	\$	30.00 <del>70.00</del> / nec
	Labour		
	Cut/Weld RH rocker panel and panel beating affected areas	\$	300.00 <del>500.00</del> ✓
	Spray painting	\$	200.00 <del>500.00</del>
	Remove and reinstall RH side inner trims, seats and all attachment to assist repair	\$	200.00 <del>NNX</del>
Total:		\$	1,787.50

T. A. Lim

16/8/2021

1600hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: