



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI21008544/T1vf3e2	
			Date: 02/09/2021	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	WB 3313U	Veh. Inspected	SBS 8418C	
Policy No.		Coverage (\$)	0.00	
Claim No.	M11D13522108	Excess (\$)	0.00	
Assign From	JOSEPHINE WONG	Assign Date	16/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	SCANIA KUB4X2	c.c	8867	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	YS2K4X20001862307	Colour	MULTI COLOUR	
Odometer	975365 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2021	Inspection Date	16/08/2021	
Survey held at	SBS TRANSIT LTD (Branch) BEDOK NORTH DEPOT 1470 BEDOK NORTH AVE 4 SINGAPORE 489946			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	