



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21008547/Gqf3e2	
			Date: 07/06/2022	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLP 7507H
	Policy No.	DHOM120034701801	Coverage (\$)	0.00
	Claim No.	M12D16252108	Excess (\$)	750.00
	Assign From	JOSEPHINE WONG	Assign Date	16/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 SEDAN 1.5	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BN22A8H0153871	Colour	BLUE
	Odometer	33885 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	TOYO	6 mm
	L/H Front Tyre	205/60 R16	TOYO	6 mm
	R/H Rear Tyre	205/60 R16	TOYO	6 mm
	L/H Rear Tyre	205/60 R16	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/07/2021	Inspection Date	19/08/2021
	Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks				
	A)THE MARKET VALUE IS S\$55,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	