



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 28-07-2018

VEHICLE NO. : SLU4345B
ACCIDENT DATE : 26-07-2018 07:40
THIRD PARTY REF. : SLB6865D

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SLU4345B VOLKSWAGEN JETTA

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BUMPER / <i>le</i>	1550.25 ? 1147.92
2	1	REAR BUMPER LOWER / <i>scr.</i>	764.68 ? 441.7
			2,314.93 1589.62
LESS 10 %			231.49
TOTAL (A)			2,083.44 1430.65

LABOUR CHARGES

1	1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE- ATING & RENEW PARTS	300.00 <i>200</i>
2	1	SPRAY PAINTING	350.00 <i>200</i>
TOTAL (D)			650.00
ESTIMATE TOTAL			2,733.44 1830.65

-20%: 1450

2 Days.

put by put.

before paint photos.

Emo Riap - 82880282

16/8/18



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: