

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	SELOTERIO EUAN IZMAL BIN ILYAS			
Ltd.	Reg No/Reg Date	SLP1900U / 24/11/202			
MOTOR CLAIM DEPT	Date In/Mileage	/ 0			
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	GF7W0700817			
SINGAPORE 079120	Engine No	4J11CQ8571			
Contact No 6419 1892	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)			
	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK			

AX00008 Credit 16/08/2021/ 12:55 261 / Edwin Caina 14184	
Description of Goods / Services Qty Unit Price Disc	c% Amount
PNT88000 3 RENEW RR BUMPER , BODY KIT , RR END PNL , TAILGATE , RHR FENDER & 5 X 450 RR FLR PNL	2250 5400.0
REPAIR ROOF TOP, RR CHASSIS & LHR FENDER PNT98000	1575
E PNT88000 REMOVE & REFIT TAILGATE COMPONENT	120.00
REMOVE & REFIT FUEL TANK ASSY	200.00
REMOVE & REFIT RE FLE BOARD TERM CARPETS TO GIVE WAY FOR REPAIR	120 200.00
PNT88000 REMOVE & REFIT HEADLINING TO FACILITATE REPAIR (phrt)	120 200.00
54900099 CHECK WIRING ELECTRICAL SYSTEM	30.00
10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	120.0
PNT88000 CONDUCT CHASSIS ALIGNEMNT-CELETTE BENCH	7 1000.0
WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment	120.0
PNT88000 RENEW RR WINDSCREEN GLASS	240.0
SUNDRY SUPPLY RR WINDSCREEN SEALANT	80.0
PNT88000	120.0
REMOVE & REINSTALL LHR FENDER QTR GLASS PNT88000 REMOVE & REINSTALL RHR FENDER QTR GLASS	120.0

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	SELOTERIO EUAN IZMAL BIN ILYA		
Ltd.	Reg No/Reg Date	SLP1900U / 24/11/202		
MOTOR CLAIM DEPT	Date In/Mileage	/ 0		
78 SHENTON WAY #09-16	Chassis No	GF7W0700817		
AIG BUILDING SINGAPORE 079120	Engine No	4J11CQ8571		
Contact No 6419 1892		MIT/20MY OUTLANDER 2.0 STYLE (999)		
	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
KAX00008	Credit	16/08/2021/ 12:55		261 / Edwin Cain	a	14184			
TO THE COURT		Description of Good	s / Services		Qty	Unit Price	Disc%		nount
M SUNDRY	`	1						+20	240.00
	LHR & RH	R FENDER QTR GLASS S	OLAR FILM						90 00
M SUNDRY									80.00
SUPPLY O	TR GLASS	SEALANT							780.00
M SUNDRY		e deltem e	dell comun)	10.11 m.					700.00
	N-CAR CA	mera (Windscrim g	1191) (umau j	- missing				50	80.00
M SUNDRY		DI ATE LITTIL CACING							
	KK NUMBER	PLATE WITH CASING					1		80.00
E PNT88000	DEETT D	EVERSE SENSOR					1		
M SUNDRY	L WELT I W	ETENSE SENSON		1	П				220.00
SUPPLY R	EVERSE SI	ENSOR DOMELL (\odot 2	1000 CO	450	į.			
M SUNDRY		1-1	5111				1	40	80.00
APPLY AN	TI CORROS	SION ON AFFECTED ARE	BU L						00 00
M SUNDRY									80.00
	ODY PNL S	SEALANT							40.00
M SUNDRY									40.00
SUPPLY C	&C BADGE								30.00
1 SUNDRY									00110
Sundries		1 00			1.00 8/1	1018.00	23.00		783.86
FACE, RR I		ER / CRU			1.00	360.00		_	277.20
BRKT, R/BA		- 110			1.00	12.00	23.00		9.24
BRKT, R/BN	IPR FACE	STOE DH / UN			1.00		23.00	_	9.24
		BUMPER, LH 1x nn	0=		1.00		23.00		60.83
		BUMPER, RH	· BT		1.00		23.00	_	60.83
CLIP, ENG		ER X MM			8.00		23.00		12.32
PANEL ASS					1.00	989.00			761.53
GARNISH, T		- RR			1.00	496.00			381.92
W/STRIP,T		OPENING ! XNN			1.00	213.00			70.84
HINGE, TAI		/ BT			2.00		23.00		149.3
GAS SPRIN					1.00	194.00			149.38
GAS SPRING	G, TAILGAT	TE,RH ? x r	11		1.00	194.00	23.00		149.30

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 4



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	SELOTERIO EUAN IZMAL BIN ILYA		
Ltd.	Reg No/Reg Date	SLP1900U / 24/11/202		
MOTOR CLAIM DEPT	Date In/Mileage	/ 0		
78 SHENTON WAY #09-16	Chassis No	GF7W0700817		
AIG BUILDING SINGAPORE 079120	Engine No	4J11CQ8571		
Contact No 6419 1892		MIT/20MY OUTLANDER 2.0 STYLE (999)		
THE PROPERTY OF THE PROPERTY O	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator			WIP No		
KAX00008	Credit	16/08/2021/ 12:55		261 / Edw	in Caina		14184		
	-	Description of Good	s / Services	3-14		Qty	Unit Price	Disc%	Amount
M SENSOR, T	ATLIGATE I					1.00	426.00	23.00	328.0
M SENSOR, T		0 0				1.00	426.00	23.00	328.0
M MOTOR, PO		1				1.00	1986.00	23.00	1529.2
M LATCH, TA		- BT				1.00		23.00	
M STRIKER.		LATCH ! - BT				1.00		23.00	14.6
M GLASS.TA						1.00	657.00	23.00	505.8
	GATE SIDE					2.00		23.00	41.5
	,WINDSHIE	44.6				4.00	6.00	23.00	18.48
	GATE, UPR	/ ncc				1.00	13.00	23.00	10.0
	WINDSHIEL					2.00		23.00	4.6
	GATE, LWR	/ N		i		1.00		23.00	31.5
	LANDER	/ 11C /	\odot 575	TO CO	0	3.00		23.00	73.1
M PANEL, RR		1 / [0] [(2111	$\Pi \cap \Omega$		1.00	326.00	23.00	251.0
	END, INR	LH 1 × NH 7	-0) (LI	шц	(91	(4.60×		23.00	
	END, INR			. — — –		1.00	146.00	23.00	112.4
M TRIM,RR		- CRV				1.00	113.00		87.0
M BOX, CARG	The Colon Co	1 CRV				1.00	204.00		157.08
M LID, CARG		BOX 1- GRV				1.00	295.00		227.1
M ANT KEYL		TION RR				1.00		23.00	73.9
		PERATIO, RR	L			1.00	91 88.00		67.7
M DUCT, RR						1.00		23.00	33.8
M PANEL, QT		/ 00				1.00	1131.00		870.8
M EXTN.QTR		LWR RH	סט			1.00		23.00	60.0
		IEL,OTR RH ? - 0	V			1.00	276.00		212.5
M GLASS, QTI						1.008			522.8
M FLOOR, RR		∠ P				1.00	751.00		578.2
M LAMP ASS						1.00	603.00		464.3
M LAMP ASS	A LOS MANAGES OF THE STATE OF	RH / BR				1.00	603.00		464.3
M LAMP ASSY		^D				1.00	506.00		389.6
M LAMP ASSY	The state of the s	- 00				1.00	506.00		389.6
M REFLECTOR		MD I H X				1.00	100.00	Control of the Contro	77.0
M REFLECTOR		MP RH 17 X				1.00	100.00		77.0
M LAMP ASSY	-7.		N			2.00	34 00	23.00	52.3

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696	ESTIMATE	GST Reg No : MR-8500111-X			
Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	SELOTERIO EUAN IZMAL BIN ILYAS			
Ltd.	Reg No/Reg Date	SLP1900U / 24/11/202			
MOTOR CLAIM DEPT 78 SHENTON WAY #09-16	Date In/Mileage	/ 0			
	Chassis No	GF7W0700817			
AIG BUILDING SINGAPORE 079120	Engine No	4J11CQ8571			
Contact No 6419 1892	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)			
	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	16/08/2021/ 12:55		261 / Edwin Caina		14184		
		Description of Good	s / Services		Qty 1	Jnit Price		Amount
M MOULDING	, RR WHEEL	L ARCH, RH	'n		1.00		23.00	129.36
M MOULDING	, RR WHEEL	L ARCH, RH / NOC			1.00		23.00	129.30
M MOULDING		ER, LH / MPC			1.00		23.00	67.70
M MOULDING					1.00		23.00	67.70
M TRIM, TA	LGATE -	- CK OR			1.00	329.00		253.33 1243.20
M BODY KI	, OUTLAN	DER GR 7 3	(ON		1.00	1554.00 511.00		408.80
M REAR SPO	DILER, COS	MIC BLUE / >	21111		1.00		23.00	27.72
			_AF					
			SIL	imat	(8)			
		REMARKS:		(LKK) 16/8/2 <u>OD-</u> N- EXC(S P/F	1, 4.20 p 1 AL 5-? 2 dy	en BeL	3	
Confirm &	accepted	y the Repairer of the foll To resurvey before/after sp To display damaged part(sp Parts prices are subject to Third party survey is on a No illegal modification(s) is	owling: pray painting s) during resurvey confirmation "Without Prejudice"		7% GST on	Ne 26799	ett 36	26,799.3 1875.5 28,675.3

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and meeded for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.