

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	SELOTERIO EUAN IZMAL BIN ILYAS		
Ltd.	Reg No/Reg Date	SLP1900U / 24/11/202		
MOTOR CLAIM DEPT	Date In/Mileage	/ 0		
78 SHENTON WAY #09-16 AIG BUILDING	Chassis No	GF7W0700817		
SINGAPORE 079120	Engine No	4J11CQ8571		
Contact No 6419 1892	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)		
	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK		

AX00008 Credit 16/08/2021/ 12:55 261 / Edwin Caina 14184	
Description of Goods / Services Qty Unit Price Disc	% Amount
RENEW RR BUMPER , BODY KIT , RR END PNL , TAILGATE , RHR FENDER & 5 X 450 RR FLR PNL	2250 5400.00
REPAIR ROOF TOP, RR CHASSIS & LHR FENDER E PNT98000	3500.00 1575
E PNT88000	120.00
REMOVE & REFIT TAILGATE COMPONENT	
A 13900099 REMOVE & REFIT FUEL TANK ASSY	200.00
REMOVE & REFIT RR FLR BOARD TRIM PROPERTY OF REPAIR	120 200.00
E PNT88000 REMOVE & REFIT HEADLINING TO FACILITATE REPAIR (ρμφ)	120 200.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM	30.00
A 10028901	120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	
PNT88000	7 1000.00
CONDUCT CHASSIS ALIGNEMNT-CELETTE BENCH B WHEELALIGNMENT	120.00
To Conduct Computerize Full Wheel Alignment	120.00
PNT88000	240.00
RENEW RR WINDSCREEN GLASS	
1 SUNDRY	80.00
SUPPLY RR WINDSCREEN SEALANT PNT88000	120.00
REMOVE & REINSTALL LHR FENDER QTR GLASS	1
PNT88000	120.00
REMOVE & REINSTALL RHR FENDER QTR GLASS	

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Pag No : 1977014696 ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696		03,
Invoice Name & Address	. 1	Owner Name & Vehicle Info
AVC Asia Danifia Ingunanca Pto	Cust No/Name	/SELOTERIO EUAN IZMAL BIN ILYAS
AIG Asia Pacific Insurance Pte.	Reg No/Reg Date	SLP1900U / 24/11/202
MOTOR CLAIM DEPT	Date In/Mileage	/ 0
78 SHENTON WAY #09-16	Chassis No	GF7W0700817
AIG BUILDING	Engine No	4J11CQ8571
SINGAPORE 079120 Contact No 6419 1892		MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK

Account No Terms Date/Time Printed CSE	Operator		WIP No			
KAX00008 Credit 16/08/2021/ 12:55	261 / Edwin Caina		14184			
Description of Goods / Services		Qty	Unit Price	Disc%	Ar	nount
M SUNDRY INSTALL LHR & RHR FENDER QTR GLASS SOLAR FILM M SUNDRY					120	240.00
SUPPLY QTR GLASS SEALANT M SUNDRY SUPPLY IN-CAR CAMERA (WINDSCHM GIGIS COMEIA)	- milling				_	780.00,
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING	- mary				50	80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR M SUNDRY		п				220.00
M SUNDRY SUPPLY REVERSE SENSOR DOMELL M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS	ma				40	80.00
M SUNDRY SUPPLY BODY PNL SEALANT		G C				80.00 /
M SUNDRY SUPPLY C&C BADGE						40.00/
M SUNDRY Sundries M FACE,RR BUMPER / PO		1.00	1018.00	23.00		783.86
M EXTENSION, RR BUMPER / CRU M BRKT, R/BMPR FACE SIDE, LH / GB		1.00		23.00		277.20 9.24 9.24
BRKT,R/BMPR FACE SIDE,RH REINFORCEMENT,RR BUMPER,LH REINFORCEMENT,RR BUMPER,RH		1.00 1.00 1.00	79.00	23.00 23.00 23.00		60.83
REINFORCEMENT, RR BUMPER, RH CLIP, ENG ROOM COVER $ imes$ PANEL ASSY, TAILGATE $ imes$ $ imes$ $ imes$		8.00 1.00	2.00 989.00	23.00 23.00		12.32 761.53
GARNISH, TAILGATE OPENING ?		1.00 1.00 2.00	496.00 213.00 46.00			381.92 164.01 70.84
HINGE, TAILGATE ! GAS SPRING, TAILGATE, LH GAS SPRING, TAILGATE, RH ?		1.00	194.00	23.00		149.38 149.38

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 4



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/SELOTERIO EUAN IZMAL BIN ILYAS		
Ltd.	Reg No/Reg Date	SLP1900U / 24/11/202		
MOTOR CLAIM DEPT	Date In/Mileage	/ 0		
78 SHENTON WAY #09-16	Chassis No	GF7W0700817		
AIG BUILDING	Engine No	4J11CQ8571		
SINGAPORE 079120 Contact No 6419 1892		MIT/20MY OUTLANDER 2.0 STYLE (999)		
distributions of plants on release to the first of the	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator	19 LE 0 1 1 1 1 -	WIP No		
KAX00008	Credit	16/08/2021/ 12:55		261 / Edwin Caina	1	14184		
		Description of Good	s / Services		Qty	Unit Price	Disc%	Amount
M SENSOR, T	ATLICATE I	OCK IN			1.00	426.00		328.0
M SENSOR, T	ATLICATE I	OCK PH			1.00	426.00		328.0
M MOTOR, PO	WED TATI	SATE			1.00	1986.00	23.00	1529.2
M LATCH, TA		n			1.00	477.00	23.00	367.2
M STRIKER,		LATCH			1.00		23.00	14.6
M GLASS, TA					1.00	657.00		505.8
M DAM, TAIL					2.00		23.00	41.5
M FASTENER		446			4.00		23.00	18.4
M DAM, TAIL		/ hic			1.00		23.00	10.0
M STOPPER,		ID GLASS / MC			2.00		23.00	4.6
M DAM, TAIL		1 NC	n E	Í	$\Box^{1.00}$		23.00	31.5
M MARK, OUT	and the second State of the second	/ NC _ (\odot $45L$	1000	5 7.90		23.00	73.1
M PANEL, RR		1",	5111		1.00	326.00		251.0
M PANEL, RR		LH 1, 1	\bigcirc		(Ly. 60)		23.00	
M PANEL, RR		RH ?		ima	1.00	146.00		112.4
M TRIM, RR					1.00	113.00		87.0
M BOX, CARG	the state of the section of	0			1.00	204.00		157.0
M LID, CARG	O FLOOR	BOX 1			1.00	295.00		227.1
ANT, KEYL					1.00		23.00	73.9
M BUZZER,K	EYLESS OF	PERATIO, RR			1.00		23.00	67.7
1 DUCT, RR	VENTILATO	OR 7			1.00		23.00	33.8
A PANEL, QT	R,OTR RH	~ 00			1.00	1131.00		870.8
4 EXTN,QTR	PANEL, RE	R LWR RH			1.00		23.00	60.0
		NEL,OTR RH ?			1.00	276.00		212.5
4 GLASS, QTI	R WINDOW,	,RH / Nec			1.00	679.00		522.8
fLOOR, RR	Λ	4			1.00	751.00		578.2
1 LAMP ASSY	The same of the sa	2.2			1.00	603.00		464.3
1 LAMP ASSY					1.00	603.00		464.3
LAMP ASSY					1.00	506.00		389.6
LAMP ASSY					1.00	506.00		389.6
A REFLECTOR	.55	(1			1.00	100.00		77.0
M REFLECTOR		wir jinit			1.00	100.00		77.0
M LAMP ASSY	,LICENSE	PLATE			2.00	34.00	23.00	52.3

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G	ESTIMATE	GST Reg No : MR-8500111-)
Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/SELOTERIO EUAN IZMAL BIN ILYAS
Ltd.	Reg No/Reg Date	SLP1900U / 24/11/202
MOTOR CLAIM DEPT	Date In/Mileage	/ 0
78 SHENTON WAY #09-16	Chassis No	GF7W0700817
AIG BUILDING SINGAPORE 079120	Engine No	4J11CQ8571
Contact No 6419 1892	Make/Model	MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim	DO1 COSMIC BLUE MET/ BK BLACK

M MOULDING, RR WHEEL ARCH, RH M MOULDING, RR WHEEL ARCH, RH M MOULDING, RR BUMPER, LH M MOULDING, RR BUMPER, LH M MOULDING, RR BUMPER, RH M M MOULDING, RB BUMPER, RH M M MOULDING, RB BUMPER, RH M M M M M M M M M M M M M M M M M M M			WIP No		ator	CSE C	Printed	Date/Time	Terms	Account No
M MOULDING, RR WHEEL ARCH, RH M MOULDING, RR BUMPER, LH M MOULDING, RR BUMPER, LH M MOULDING, RR BUMPER, RH M M MOULDING, RB BUMPER, RH M M M M M M M M M M M M M M M M M M M					/ Edwin Caina	2	1/ 12:55	16/08/202	Credit	KAX00008
M MOULDING, RR INHEEL ARCH, RH M MOULDING, RR BUMPER, LH M MOULDING, RR BUMPER, RH M MOULDING, RR BUMPER, LH M M M MOULDING, RB BUMPER, LH M M M MOULDING, RB BUMPER, LH M M M M M M M M M M M M M M M M M M M	mount			Qty L		/ Services	on of Goods	Descripti		
M MOULDING, RR BUMPER, RH	129.30			1.00			17	ARCH, LH	, RR WHEEL	M MOULDING
M MOULDING, RR BUMPER, RH	129.36		ARREST SE ROOM OF	1.00			186	ARCH, RH	, RR WHEEL	M MOULDING
TRIN, TAILGATE M BODY KIT, OUTLANDER M REAR SPOILER, COSMIC BLUE M DECAL, MIVEC OF SURVEYOR NAME: SURVEYOR NAME: SURVEYOR SIGNATURE: DATE: REMARKS: I.00 329.00 23.00 1.00 1.00 1.00 1511.00 20.00 1.00 36.00 23.00 1.00 ACCURATE STATEMENT STATEMENT SURVEYOR SIGNATURE: EXCLUSIVE STATEMENT STATEMENT SURVEYOR SIGNATURE: REMARKS: 1.00	67.76						MPC	ER,LH /	RR BUMP	M MOULDING
M BODY KIT, OUTLANDER M REAR SPOILER, COSMIC BLUE M DECAL, MIVEC M DECAL, M	67.76						V(C			
SURVEYOR NAME: Steve (LKK) 16/8/11, 4.90 pm SURVEYOR SIGNATURE: DATE: REMARKS: LKK Auto Consultants hence notify	253.33						0.0	- CK	ILGATE -	M TRIM, TAI
SURVEYOR NAME: Steve (LKK) 16/8/11, 4.90 pm SURVEYOR SIGNATURE: DATE: REMARKS: LKK Auto Consultants hence notify	1243.20						BKa	DER /	T, OUTLAN	M BODY KIT
Steve (LKK) 16/8/21, 490 pm SURVEYOR NAME: Steve (LKK) 16/8/21, 490 pm SURVEYOR SIGNATURE: OD- NM AL EXCLUSIS - ? DATE: PIP, M Bel SM REMARKS: 12 dys	27.72		Medicine of Events of the				2	HIC DECE		
SURVEYOR NAME: Steve (LKK) 16/8/21, 4.90 p. P.1 SURVEYOR SIGNATURE: DD- NM AL EXC(SS-? DATE: PIP, M Bel M EKK Auto Consultants hence notify					നമ	a 6 1 1 1 1 1 1	F			
REMARKS:				G C		3) [FII]	L_ 7			
REMARKS:								*		
REMARKS:			P)	1, 4.90p	(K) 16/8/2	Chaup (
REMARKS:				JAL	00- N	Steve C	YOR NAME:	SURVE		
REMARKS:		1		55 - 7	EXCU	URE:	EYOR SIGNAT	SURV		
REMARKS:			0.7	1 0	- LAC	122				
LKK Auto Consultants hence notify		1	KeL Q 1		0/1		:	DATE		
LKK Auto Consultants hence notify		71	0. 40]	1 , 1			DKS .	DEMA		
LKK Auto Consultants hence notify			S	2 ds	/		11110.	KEWIP		
			201							
		1			1	ence notify	Consultante I	LIVIVALIG		
the Repairer of the following:					1			the Denni		222 2922
Confirm & accepted by To resurvey before/after spray painting						ay painting	y before/after sp	To resurve	accepted	Confirm &
To display damaged part(s) during resurvey	26,799.					during resurvey	damaged part(s)	 To display 		
Parts prices are subject to confirmation 7% GST on 26799.36			26799.36	7% GST on		onfirmation	es are subject to	Parts price		
Third party survey is on a "Without Prejudice" basis	1875.9				E .	Vithout Prejudice' ba	v survey is on a "	 Third party 		
No illegal modification(s) is allowed Total Payable			and Research		1					
Supplementary item(s) must be resurveyed and Authorized signatory and company all from Insurance Company	1875.5 28,675.5		tal Payable	To		allowed	modification(s) is	No illegal		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and seeded for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen. the rubber seal or other repair requiring the removal of the windscreen.