

ASS. REC. BY: Tanjah REF: CC4/A1621008556/T1p93

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SUC6405R Yr Regn: 20151 March
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Kia Optima c.c. 1685
Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 723355 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ICNA 9M414M-E5588606
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modl: NI / S/Rim / STD A/Rim or
Tyre Size: F: 205/65R15
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Maxxis
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 16/8/21
Survey held at Premier Auto
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt N/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2) _____

Rep. Format :

Lump Sum / L.B.A. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6405 R

1 pc	Front n/s head lamp	\$	1,028.00 X
1 pc	Front bumper emblem	\$	44.00 <i>neu</i>
1 pc	Front bumper	\$	531.00 <i>de</i>
1 pc	Front bumper n/s side retainer	\$	16.00 <i>neu</i>
1 pc	Front bumper n/s upper bracket	\$	16.00 ?
1 pc	Front bumper n/s support bracket	\$	16.00 ?
1 pc	Front n/s fender	\$	384.00 <i>bt</i>
1 pc	Front n/s fender inner shield	\$	120.00 ?
1 pc	Front n/s lower arm	\$	439.00 X
1 pc	Front n/s shock absorber	\$	330.00 X
1 pc	Front n/s ball joint	\$	59.00 X
1 pc	Front n/s tie rod end	\$	61.00 X
1 pc	Front n/s knuckle bearing	\$	157.00 ?
1 pc	Front n/s stabilizer link	\$	86.00 X
1 pc	Front n/s knuckle arm	\$	547.00 ?
1 pc	Front n/s rim	\$	246.00 ?
1 pc	Front n/s wheel cover	\$	116.00 <i>de</i>
		\$	4,196.00
		Less 10%	\$ 419.60
			\$ 3,776.40

S/NETT

1 set	Front n/s fender inner shield clips	\$	28.00 ?
1 set	Front bumper clips	\$	48.00 <i>30m</i>
1 pc	Front n/s fender sticker	\$	60.00 <i>30m</i>
1 set	n/s door stickers	\$	100.00 X

16-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6405 R

Sundry fee	\$ 50.00 X
To check wheel alignment	\$ 80.00 ✓
To check headlamp wiring	\$ 40.00 30
To dismantle and replace front n/s undercarriage	\$ 250.00 150? photo
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 X
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s door, front n/s wheel house etc	\$ 900.00 300
To putty and spray painting on front bumper, front n/s fender, front n/s door, front n/s wheel house, n/s mirror cover	\$ 900.00 400
To apply rustproofing on the repaired and replaced panels.	\$ 150.00 30
	<u>\$ 6,562.40</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanphie 97495749
WP 16/8/21 @ 1515
1/2 Resurvey after repair
Tanphie @ LKK auto. con.
2-3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time: 19 Mar 2015 / 09:03:38
Asset Type: Vehicle
Asset ID: SHC6405R
Transaction Type: 01.02 Register New Vehicle (AA)
Business Transaction Reference No.: 20150319090338000208

Receipt No.: AACCK001-AX239-150319-000002
Transaction Amount: \$65,391.00
Channel: AA Counterless - CYCLE & CARRIAGE KIA PTE LTD

Vehicle No.: SHC6405R
Vehicle Type: H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Scheme: Taxi (Company)
First Registration Date: 19 Mar 2015
Original Registration Date: 19 Mar 2015
Vehicle Make: KIA
Vehicle Model: OPTIMA 1.7(A) DIESEL
Chassis No.: KNAGM414MF5588606
Engine No.: D4FDEH313575
Motor No.: -
Trailer Chassis No.: -
Propellant: Diesel
Passenger Capacity: 4
Engine Capacity: 1685
Power Rating: -
Unladen Weight: 1584
Maximum Laden Weight: 2050
Primary Color: Silver
Secondary Color: -
Manufacturing Year: 2014
Open Market Value: \$21,185.00
Minimum PARF Benefit: \$8,495.00
PARF Eligibility: Y
No. of Transfer: 0
Effective Ownership Date/Time: 19 Mar 2015 09:03:38
COE No.: 2015031901002262G
COE Expiry Date: 18 Mar 2023
COE Bid Category: -
Actual QP/PQP Paid Amount: \$51,092.00
Lifespan Expiry Date: 18 Mar 2023