

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6405 R

1 pc	Front n/s head lamp	\$	1,028.00	Xun,
1 pc	Front bumper emblem	\$	44.00	rec
1 pc	Front bumper	\$	531.00	de
1 pc	Front bumper n/s side retainer	\$	16.00	rec
1 pc	Front bumper n/s upper bracket	\$	16.00	Xun
1 pc	Front bumper n/s support bracket	\$	16.00	de
1 pc	Front n/s fender	\$	384.00	de
1 pc	Front n/s fender inner shield	\$	120.00	?
1 pc	Front n/s lower arm	\$	439.00	X
1 pc	Front n/s shock absorber	\$	330.00	X
1 pc	Front n/s ball joint	\$	59.00	X
1 pc	Front n/s tie rod end	\$	61.00	X
1 pc	Front n/s knuckle bearing	\$	157.00	?
1 pc	Front n/s stabilizer link	\$	86.00	X
1 pc	Front n/s knuckle arm	\$	547.00	?
1 pc	Front n/s rim	\$	246.00	?
1 pc	Front n/s wheel cover	\$	116.00	de
		\$	4,196.00	1091
Less 10%		\$	419.60	981.90
		\$	3,776.40	

S/NETT

1 set	Front n/s fender inner shield clips	\$	28.00	Xun
1 set	Front bumper clips	\$	48.00	30M
1 pc	Front n/s fender sticker	\$	60.00	30M
1 set	n/s door stickers	\$	100.00	Xun

60

16-Aug-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6405 R

Sundry fee	\$	50.00	Xm
To check wheel alignment	\$	80.00	✓
To check headlamp wiring	\$	40.00	? 33xm
To dismantle and replace front n/s undercarriage	\$	250.00	150xm photo
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	Xm
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s door, front n/s wheel house etc			300
	\$	900.00	
To putty and spray painting on front bumper, front n/s fender, front n/s door, front n/s wheel house, n/s mirror cover			400
	\$	900.00	
To apply rustproofing on the repaired and replaced panels.			30
	\$	150.00	
	\$	6,562.40	820

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanaka 97495749
WP' 16/8/21 1515 1851.90
1/3 Resurvey after repair 1/3 \$1450
Tanaka 97495749 3 days.
2-3 days.

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>
