



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D
61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047
Email: jeslyn@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

Insurance Company:	MS First Capital Insurance Ltd		
	Motor Claims Department		
Address:	30 Robinson Road #10-01/02 Robinson Towers Singapore 048546		
Telephone:		Fax:	
Make/ Model :	HONDA STREAM 1.8X A	Date:	13/8/2021
Chassis No :	RN61064659	Vehicle No:	SJG520K
Date/Time of Accident :	13/8/2021 10:30		

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	TAIL GATE <i>one</i>	1	\$ 903 1,100.00	20%	\$ 880.00
2	TAIL GATE OUTER GARNISH <i>MSG</i>	1	\$ ✓ 195.00	20%	\$ 156.00
3	TAIL GATE LOGO <i>SAGE</i>	1	\$ ✓ 30.00	20%	\$ 24.00
4	TAIL GATE EMBLEM STREAM	1	\$ ✓ 38.00	20%	\$ 30.40
5	TAIL GATE WEATHERSTRIP <i>Tur;</i>	1	\$ ✓ 160.00	20%	\$ 128.00
6	TAIL GATE SHOCKABSOBER <i>2 SH JPHX</i>	1	\$ 118.6 145.00	20%	\$ 116.00
7	TAIL GATE INNER TRIM <i>2 BLC</i>	1	\$ ✓ 170.00	20%	\$ 136.00
8	TAIL GATE TOP LOCK <i>XNN</i>	1	\$ ✓ 130.00	20%	\$ 104.00
9	TAIL GATE TOP LOCK CENTRAL LOCKING <i>XNN</i>	1	\$ 175.00	20%	\$ 140.00
10	TAIL GATE STOPPER <i>X NN</i>	2	\$ 26.00	20%	\$ 20.80
11	REAR BUMPER <i>TR</i>	1	\$ 588.6 810.00	20%	\$ 648.00
12	REAR BUMPER SIDE RETAINER <i>2 LH X NN</i>	2	\$ 19.4 46.00	20%	\$ 36.80
13	REAR BUMPER TOW COVER <i>1 BH</i>	1	\$ ✓ 16.00	20%	\$ 12.80
14	REAR BUMPER LOWER BRACKET <i>X</i>	2	\$ 26.00	20%	\$ 20.80
15	REAR TAIL LAMP <i>1 Cnt</i>	2	\$ 705.6 980.00	20%	\$ 784.00
16	REAR END PANEL TOP AND BOTTOM <i>2 BLC</i>	1	\$ 306.7 400.00	20%	\$ 320.00
18	REAR END PANEL TOP GARNISH <i>2 BR</i>	1	\$ 128 175.00	20%	\$ 140.00
19	REAR END PANEL TOP GARNISH COVER <i>2 BR</i>	1	\$ ✓ 65.00	20%	\$ 52.00
20	REAR TOWING HOOK COVER <i>X NN</i>	1	\$ 16.00	20%	\$ 12.80
21	REAR WIPER ARM COVER <i>X Cnt</i>	1	\$ 32.2 75.00	20%	\$ 60.00
22	REAR CHASSIS END PANEL JOINT <i>X</i>	2	\$ 196.00	20%	\$ 156.80
23	REAR FLOOR PANEL TOP BOARD <i>X</i>	2	\$ 300.00	20%	\$ 240.00
24	REAR FLOOR PANEL TOP BOARD HOLDER <i>X</i>	1	\$ 26.00	20%	\$ 20.80
TOTAL LIST COST PRICE & AFTER DISCOUNT					\$ 4,240.00

3606.1

2884.88

SPECIAL NETT ITEM

SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$		FINAL PRICE \$
1	TAIL GATE OUTER GARNISH CLIPS <i>/ 500</i>	2	\$ 10.00		\$ 10.00
2	REAR BUMPER CLIPS <i>/ 500</i>	2	\$ 10.00		\$ 10.00
3	REAR REVERSE SENSOR <i>/ 500</i>	4	\$ 220.00		\$ 220.00
4	REAR REVERSE CAMERA <i>/ 500</i>	1	\$ 640.00		<i>250</i> 640.00
5	REAR NUMBER PLATE <i>/ 500</i>	1	\$ 50.00		<i>40</i> 50.00
TOTAL SPECIAL NETT ITEM					\$ 930.00

530

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE AND RENEW <u>REAR</u> DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	\$ 1,600.00

500 700

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,400.00

600

Labour Works

Job Scope	Quotation
TO REMOVE/ REFIX WIRING CHECKS	\$ 60.00
TO TUFFCOAT AFFECTED AREA	\$ 120.00
TO REMOVE AND REFIT <u>REAR</u> WINDSCREEN	\$ 150.00
TO DIAGNOSE AND RESET AIRBAG	\$ 200.00
OTHER LABOUR COST	\$ 530.00

*30
60
120
30*

1540

GRAND TOTAL \$ 8,700.00

Jeslyn

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Job Title: Motor Claim
Mobile: 65 9380 9969
Email: jeslyn@carzauto.com.sg

*6 Days.
Lumpsum repair
After repair photos.*

4954.88

-20%: 3950

Caro Q: amp - 82880282

*Caro Q: Amg @ lkk auto. com
16/8/2021*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____