



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2108711

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 20/12/2021  
Reference CC6/CTI21008562/Uea3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SLS 6155E  
Insured Veh. SLW 3365P  
Claim No. SNM21D204594/C02/SLW3365P/TANKL  
Policy No. DMHCSNA00005072001  
Accident Date 14/08/2021  
Inspection Date 16/08/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                 |                             |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------|-----------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                           |                 | Ref: CC6/CTI21008562/Uea3q2 |  |
|                                                                                                                                        |                                                                                           |                 | Date: 20/12/2021            |  |
|                                                                                                                                        |                                                                                           |                 | Code: CTI                   |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                 |                             |  |
| Insured Veh.                                                                                                                           | SLW 3365P                                                                                 | Veh. Inspected  | SLS 6155E                   |  |
| Policy No.                                                                                                                             | DMHCSNA00005072001                                                                        | Coverage (\$)   | 0.00                        |  |
| Claim No.                                                                                                                              | SNM21D204594/C02/SLW3365<br>P/TANKL                                                       | Excess (\$)     | 0.00                        |  |
| Assign From                                                                                                                            |                                                                                           | Assign Date     | 16/08/2021                  |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                 |                             |  |
| Make & Model                                                                                                                           | TOYOTA SIENTA (A)                                                                         | c.c             | 1496                        |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.    | 2020                        |  |
| Chassis No.                                                                                                                            | MHFZ28H3500068412                                                                         | Colour          | GREY                        |  |
| Odometer                                                                                                                               | 10425 KM                                                                                  | Steering        | IN ORDER                    |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                  | Modification    | SPORTS RIM                  |  |
| General                                                                                                                                | FAIR                                                                                      |                 |                             |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                 |                             |  |
|                                                                                                                                        | Size                                                                                      | Make            | Balance                     |  |
| R/H Front Tyre                                                                                                                         | 185/60 R15                                                                                | DUNLOP          | 6 mm                        |  |
| L/H Front Tyre                                                                                                                         | 185/60 R15                                                                                | DUNLOP          | 6 mm                        |  |
| R/H Rear Tyre                                                                                                                          | 185/60 R15                                                                                | DUNLOP          | 6 mm                        |  |
| L/H Rear Tyre                                                                                                                          | 185/60 R15                                                                                | DUNLOP          | 6 mm                        |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                 |                             |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION.<br><br>DAMAGES SEE DETAILS.         |                                                                                           |                 |                             |  |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                 |                             |  |
| Accident Date                                                                                                                          | 14/08/2021                                                                                | Inspection Date | 16/08/2021                  |  |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                 |                             |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                 |                             |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                 |                             |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                           |                 |                             |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                           |                 | 7 Working Days              |  |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 6155E

| Qty | Description of Parts                | Condition          | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-------------------------------------|--------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>  |                    |                           |                   |
| 1   | REAR WINDSCREEN                     | NOT NECESSARY      | 1,699.10                  | -                 |
| 1   | REAR WINDSCREEN MOULDING            | NECESSARY          | 118.00                    | 104.60            |
| 1   | TAILGATE                            | BADLY DENTED       | 1,655.40                  | 1,181.90          |
| 1   | TAILGATE OUTER HANDLE GARNISH       | CRACKED            | 425.10                    | 369.20            |
| 1   | TAILGATE REAR LOGO                  | NECESSARY          | 68.50                     | 68.50             |
| 1   | TAILGATE 'SIENTA' EMBLEM            | NECESSARY          | 62.00                     | 52.50             |
| 2   | TAILGATE REFLECTORS @\$680.10       | O/S SCRATCHED      | 1,360.20                  | 361.90            |
| 1   | TAILGATE REAR WIPER BLADE           | NOT NECESSARY      | 66.00                     | -                 |
| 1   | TAILGATE REAR WIPER ARM             | NOT NECESSARY      | 108.00                    | -                 |
| 1   | TAILGATE REAR WIPER MOTOR           | NOT NECESSARY      | 625.40                    | -                 |
| 1   | TAILGATE WEATHERSTRIP               | TWISTED            | 329.00                    | 299.40            |
| 1   | TAILGATE INNER LOCK                 | BENT               | 345.50                    | 381.55            |
| 1   | TAILGATE INNER TRIM                 | DEFORMED / TORN    | 322.20                    | 322.20            |
| 1   | SET TAILGATE INNER TRIM CLIPS       | NECESSARY          | 50.00                     | 50.00             |
| 1   | TAILGATE INNER HOLDER GARNISH       | NOT NECESSARY      | 52.00                     | -                 |
| 2   | TAILGATE DAMPERS @\$280.10          | NOT NECESSARY      | 560.20                    | -                 |
| 1   | REAR BUMPER                         | DISTORTED          | 1,415.10                  | 651.90            |
| 1   | REAR BUMPER CENTRE BLACK GARNISH    | DISTORTED          | 399.80                    | 281.80            |
| 1   | REAR BUMPER OUTER BLACK GARNISH O/S | DISTORTED          | 199.30                    | 181.60            |
| 2   | REAR BUMPER REFLECTORS @\$68.00     | NOT NECESSARY      | 136.00                    | -                 |
| 2   | REAR BUMPER SIDE RETAINERS @\$95.10 | O/S CRACKED        | 190.20                    | 68.50             |
| 1   | REAR BUMPER SPONGE                  | NO SUCH PARTS      | 188.50                    | -                 |
| 1   | SET REAR BUMPER CLIPS               | NECESSARY          | 50.00                     | 50.00             |
| 1   | REAR END PANEL                      | BADLY DENTED       | 988.50                    | 796.90            |
| 1   | REAR END PANEL TOP GARNISH          | TWISTED            | 245.60                    | 214.30            |
| 1   | REAR END PANEL SMART SENSOR         | NOT NECESSARY      | 305.10                    | -                 |
| 1   | REAR FLOOR PANEL                    | CRUMPLED / BUCKLED | 1,655.20                  | 1,425.50          |
| 1   | REAR FLOOR PANEL TOP BOARD          | WARPED             | 545.10                    | 518.50            |
| 1   | REAR FLOOR PANEL TOP TRAY           | TWISTED            | 522.00                    | 499.20            |
| 2   | TAILLAMPS @\$788.10                 | O/S CRACKED        | 1,576.20                  | 498.60            |

Report Ref No. CC6/CTI21008562/Uea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                          | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|-----------------------------------------------|----------------------|---------------------------|-------------------|
| 2   | TAILLAMP HOUSING PANELS @\$425.10             | TO REPAIR SEE LABOUR | 850.20                    | -                 |
| 2   | REAR FENDERS @\$1205.10                       | TO REPAIR SEE LABOUR | 2,410.20                  | -                 |
| 2   | REAR FENDER INNER TRIM BOARDS @\$655.10       | O/S DISTORTED        | 1,310.20                  | 545.10            |
| 2   | REAR FENDER OUTER TOP GARNISHS @\$645.50      | O/S CRACKED          | 1,291.00                  | 588.20            |
| 1   | REAR EXHAUST                                  | TO REPAIR SEE LABOUR | 899.50                    | -                 |
| 1   | REAR EXHAUST HEAT SHIELD                      | NOT NECESSARY        | 175.60                    | -                 |
| 1   | REAR EXHAUST MOUNTING                         | NOT NECESSARY        | 50.00                     | -                 |
| 1   | REAR CHASSIS MEMBER O/S                       | TO REPAIR SEE LABOUR | 625.00                    | -                 |
| 1   | SLIDING DOOR O/S                              | TO REPAIR SEE LABOUR | 1,215.10                  | -                 |
| 1   | REAR AIR VENT                                 | NOT NECESSARY        | 85.00                     | -                 |
| 1   | REAR SPLASH SHIELD O/S                        | TORN                 | 98.50                     | 98.50             |
|     | LESS 25% DISCOUNT                             |                      | -                         | -2,402.59         |
|     |                                               |                      | 25,273.50                 | 7,207.76          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>              |                      |                           |                   |
| 1   | REAR WINDSCREEN SEALANT (SN)                  | NECESSARY            | 50.00                     | 40.00             |
| 1   | REAR WINDSCREEN INNER SEAL (SN)               | NECESSARY            | 50.00                     | 30.00             |
| 1   | REAR LICENCE PLATE (SN)                       | SERVICEABLE          | 50.00                     | -                 |
| 1   | SET REAR BUMPER REVERSE SENSOR (SN)           | SHORTED              | 280.00                    | 200.00            |
| 1   | REAR END PANEL SEALANT (SN)                   | NECESSARY            | 50.00                     | 50.00             |
| 1   | SET REAR FLOOR PANEL INSULATOR (SN)           | NECESSARY            | 250.00                    | 120.00            |
| 1   | REAR FENDER GLASS SEALANT OS (SN)             | NOT NECESSARY        | 50.00                     | -                 |
|     |                                               |                      | 780.00                    | 440.00            |
|     | <b><u>LABOUR</u></b>                          |                      |                           |                   |
|     | TO CHECK WIRING .                             |                      | 50.00                     | 30.00             |
|     | TO DISMANTLE & REPLACED REAR REVERSE SENSOR . |                      | 80.00                     | 50.00             |
|     | TO DISMANTLE & REFIX REAR WINDSCREEN .        |                      | 150.00                    | 120.00            |
|     | TO TRANSFER TAILGATE MECHANISM .              |                      | 100.00                    | 60.00             |
|     | TO DISMANTLE & REFIX CUSHION UPHOLSTERY .     |                      | 150.00                    | 100.00            |
|     | TO MOUNT VEHICLE ON CAR O-LINER.              | NOT NECESSARY        | 380.00                    | -                 |

Report Ref No. CC6/CTI21008562/Uea3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                         | Description of Parts                                                                                                                                                    | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
|                                                                             | TO DISMANTLE & REFIX REAR EXHAUST .                                                                                                                                     | NOT NECESSARY | 100.00                    | 60.00             |
|                                                                             | TO SPRAY RUST PROOFING .                                                                                                                                                |               | 120.00                    | 90.00             |
|                                                                             | TO RESET & REPROGRAMME SYSTEM.                                                                                                                                          |               | 180.00                    | -                 |
|                                                                             | LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS ,REAR FENDERS,REAR EXHAUST ,REAR CHASSIS MEMBER O/S AND SLIDING DOOR O/S . |               | 2,200.00                  | 1,500.00          |
|                                                                             | TO PUTTY & SPRAY PAINTING.                                                                                                                                              |               | 1,800.00                  | 1,400.00          |
|                                                                             |                                                                                                                                                                         |               | 5,310.00                  | 3,410.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                         |               | <b>31,363.50</b>          | <b>11,057.76</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                         |               |                           | <b>8,800.00</b>   |

Report Ref No. CC6/CTI21008562/Uea3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLS 6155E

### INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 6155E

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 6155E

RE-INSPECTION

