

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Monday, 30 August 2021 11:13 am
To: Shiau Chan (LKKAUTO)
Subject: RE: ASM-TP SME 6767B SURVEYED BY KENNETH (OUR REF: CS/ASM21008564/Kqc)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SME6767B, FOUND NO WHEEL ALIGNMENT REPORT FOR UNDERCARRIAGE PARTS REPLACED.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 26 August, 2021 4:35 PM
To: Simon Ho (LKKAUTO)
Subject: ASM-TP SME 6767B SURVEYED BY KENNETH (OUR REF: CS/ASM21008564/Kqc)

Dear Simon,

For your audit.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)