

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 06 Sep 2021

Preliminary Advice

Insured Vehicle No : SLK5576Y
TP Vehicle No : SKT9903A
Make : TOYOTA NOAH HYBRID
Date of Inspection : 31/08/2021
Inspection At : MBM WHEELPOWER PTE LTD (SIN MING)
176 SIN MING DRIVE #01-15, SIN MING AUTOCARE
SINGAPORE 575721
Accident Date : 12/08/2021
Assignment Date : 17/08/2021
Est. Duration of Repair : 4

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,505.00
Revised Amount	:S\$	2,370.00
Check Items (Estimated)	:S\$	135.00
Total	:S\$	2,505.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- () The above survey was conducted on a 'without prejudice' basis.